

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2024

Submitted Date:

11/20/2024

Document Number:

707603367**FIELD INSPECTION FORM**Loc ID 305117 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274329	WELL	SI	03/01/2024	OW	123-22517	FRANCIS 11-8	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / WORKOVER / CEMENTING** inspection.

Well(s): 1: Plugged & Abandoned | PA.

Plugging Operations: Cementing; Cement-surface.

Battery: Inactive. Shut-down.

Inactive Battery SE corner GPS coordinates: 40.505344 / -104.583273

Well GPS coordinates: 40.506440 / -104.581970

Location**Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 0		corrective date
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	274329	Type:	WELL	API Number:	123-22517	Status:	SI	Insp. Status:	PA
Cement									
Cement Contractor									
Contractor Name: Duco Services					Contractor Phone:				
Surface Casing									
Cement Volume (sx):					Circulate to Surface:				
Cement Fall Back:					Top Job, 1" Volume:				
Intermediate Casing									
Cement Volume (sxs):					Good Return During Job:				
Production Casing									
Cement Volume (sx):					Good Return During Job:				
Plugging Operations									
Depth Plugs(feet range): 6692'-3595'-2772'-0'					Cement Volume (sx): 112 sxs				
Good Return During Job:					Cement Type: Class "G" Neat 15.8#				
Comment: 2024/11/19: Plugging Operations: Cementing; cement-surface. 2024/11/19: JSA attached as photo to this report. Workover Contractor: Ensign Energy Services Rig #356. Cement Contractor: Duco Services. IWP- 0 PSI ON SURFACE CASING (NO BUBBLES) 0 PSI ON CASING HELD SAFETY MEETING. REVIEW SYLA'S. PERFORM SWC'S AND INSPECTIONS (WSEA-2-A). CHECKED FOR PRESSURE/FLOW (WSEA-10C). HELD SAFETY MEETING WITH RANGER WIRELINE (WSEA-2A). RU WIRELINE. SET CIBP AT 6692'. BAILED 2 SACKS. LOADED HOLE WITH FRESH WATER. PRESSURE TESTED CASING/CIBP TO 1500 PSI (WSEA-10B). SET CIBP AT 3595'. BAILED 2 SACKS. SET CIBP AT 2772'. RD WIRELINE. TIH W/ 90 JOINTS OF 2 3/8 4.7# J-55 8RD EUE TUBING. HELD SAFETY MEETING WITH DUCO CEMENT. RU CEMENT UNIT. PUMPED 5BBLs FRESH WATER. PUMPED 10 SACKS NEAT G. PUMPED 10BBLs DISPLACEMENT. RD CEMENT UNIT. LAID DOWN59 JOINTS OF 2 3/8 4.7# J-55 8RD EUE TUBING. EOT 699'. RU CEMENT UNIT. PUMPED 98 SACKS NEAT G. LAID DOWN 31 JOINTS OF 2 3/8 4.7# J-55 8RD EUE TUBING. RD FLOOR. ND BOP'S. TOPPED OFF WELL. NU WH. RD CEMENT UNIT. RD SERVICE UNIT. DRAINED HARDLINE AND PUMP. RD HARDLINE. CLEANED LOCATION. LOCKED/TAGGED OUT WELL. SHUT DOWN.									
Corrective Action:								Date:	
Workover									
Comment: 2024/11/19: Plugging Operations: Cementing; cement-surface. 2024/11/19: JSA attached as photo to this report. Workover Contractor: Ensign Energy Services Rig #356. Cement Contractor: Duco Services. Reference: Form 6N on file. Notice of Intent to Abandon date: 10/25/2024. Approved. Form 42 on file. Notice of MIRU. Start Date: 11/18/2024. Approved. Form 42 on file. Notice of Plugging Operations. Start Date: 11/18/2024. Approved.									

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On TUE 11/19/2024 at approximately 13:29 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: FRANCIS-66N64W/8NWNW Location ID: 305117 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations: Cementing; Cement-surface. Battery: Inactive. Shut-down. Inactive Battery SE corner GPS coordinates: 40.505344 / -104.583273 Well GPS coordinates: 40.506440 / -104.581970</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	11/20/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603368	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6794453