

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/19/2024

Submitted Date:

11/20/2024

Document Number:

707603376

FIELD INSPECTION FORM

Loc ID: 323413 Inspector Name: Evins, Bret On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
 Name of Operator: NOBLE ENERGY INC
 Address: 1099 18TH STREET SUITE 1500
 City: DENVER State: CO Zip: 80202

Findings:

13 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
323413	LOCATION	AC			-	RAY-GLO-66N64W 14NENW	IO

General Comment:

This is a BATTERY inspection.
 Well(s): 1: Temporarily Abandoned | TA.
 Battery: Inactive | Shut-down.

Centralized Battery serves 1 Location ID (323413).
 (Well(s): 1: Temporarily Abandoned | TA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference (Associated Well(s), Battery Inspections):
 A.) Field Inspection Report doc. #707603374 and/or Location ID #323413 for TA Well(s) info.
 B.) Field Inspection Report doc. #707603376 and/or Location ID #323413 for Battery / Facility, Equipment info.

Location

Lease Road:			
	Type	Access	
	comment:	Adequate	
	Corrective Action:		Date:

Overall Good:

Signs/Marker:			
	Type	OTHER	
	Comment:	Battery site: OOSLAT applied.	
	Corrective Action:		Date:
	Type	TANK LABELS/PLACARDS	
	Comment:		
	Corrective Action:		Date:
	Type	BATTERY	
	Comment:	*Refer to Emergency Contact Number section below.	
	Corrective Action:		Date:

Emergency Contact Number:			
	Comment:	<p>CORRECTIVE GUIDANCE COMMENT: During this inspection the following possible compliance issue(s) were observed: 1.) Invalid Emergency contact number posted on Battery signage. Refer to Rule 605.e for guidance. *Post valid emergency contact number on Battery signage. Comply with Rule 605.e. See photo(s) #5. *Please provide photo(s) via email to "bret.evins@state.co.us" to verify Corrective Guidance Item(s) have been addressed.</p>	
	Corrective Action:		Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type	SEPARATOR	
	Comment:	No fencing. Surrounded by earth berms.	
	Corrective Action:		Date:
	Type	TANK BATTERY	
	Comment:	Braided wire.	
	Corrective Action:		Date:

Equipment:		corrective date
Type: Gas Meter Run	# 1	

Comment: 1: Gas Sales, Master; (Phillips 66). Calibration card(s) indicates calibration > 1 year. Last calibration: 08/12/2015. Designated TD (Temp Disconnect).			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:		Centralized Battery serves 1 Location ID (323413). (Well(s): 1: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).			
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	53 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Berms shared w/ crude oil tank(s), produced H2O vault(s).					
Corrective Action:				Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.493158,-104.519617
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Berms shared w/ crude oil tank(s), produced H2O vault(s).					
Corrective Action:				Date:	

Wells Served By Facilities Above	AirsID
API Number	API Number AirsID
123-12985	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 323413 Type: LOCATION API Number: - Status: AC Insp. Status: IO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On TUE 11/19/2024 at approximately 14:58 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Facility Name: Pending Facility ID: Pending Location Name: RAY-GLO-66N64W/14NENW Location ID: 323413 Well Name(s): See photo(s) #6 attached to this report. API: See "Wells Served By Facilities Above" sec on pg. 4 and/or photo(s) #6 attached to this report. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	11/20/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603377	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6794457