

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2024

Submitted Date:

11/20/2024

Document Number:

713301253**FIELD INSPECTION FORM**Loc ID 317981 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name   | Phone        | Email                     | Comment                         |
|----------------|--------------|---------------------------|---------------------------------|
| Silver, Randy  | 720-827-6688 | randy.silver@state.co.us  |                                 |
| , KPK          | 303-825-4822 | cogcc@kpk.com             | <a href="#">all inspections</a> |
| Pesicka, Conor |              | conor.pesicka@state.co.us |                                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 240299      | WELL | PR     | 08/01/2024  | OW         | 123-08087 | UPRR 43 PAN AM G 2 | PR          |

**General Comment:**[follow up inspection](#)

**Location**Overall Good: ☒**Signs/Marker:**

|                    |             |       |  |
|--------------------|-------------|-------|--|
| Type               | WELLHEAD    |       |  |
| Comment:           | rusty/faded |       |  |
| Corrective Action: |             | Date: |  |

Emergency Contact Number:

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  | Date: |  |
| Corrective Action: |  |       |  |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | LOCATION                                |       |  |
| Comment:           | post and wire                           |       |  |
| Corrective Action: |   | Date: |  |
| Type               | OTHER                                   |       |  |
| Comment:           | automation/electric panel, metal panels |       |  |
| Corrective Action: |   | Date: |  |
| Type               | PUMP JACK                               |       |  |
| Comment:           | safety guard                            |       |  |
| Corrective Action: |   | Date: |  |

**Equipment:**

|                           |                            |       |                 |
|---------------------------|----------------------------|-------|-----------------|
| Type: Prime Mover         | # 1                        |       | corrective date |
| Comment:                  | electric                   |       |                 |
| Corrective Action:        |                            | Date: |                 |
| Type: Bradenhead          | # 1                        |       |                 |
| Comment:                  | pipied to surface          |       |                 |
| Corrective Action:        |                            | Date: |                 |
| Type: Pump Jack           | # 1                        |       |                 |
| Comment:                  |                            |       |                 |
| Corrective Action:        |                            | Date: |                 |
| Type: Ancillary equipment | # 3                        |       |                 |
| Comment:                  | electric/automation panels |       |                 |
| Corrective Action:        |                            | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 240299 Type: WELL API Number: 123-08087 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTED

Comment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Valves appeared to be closed at time of inspection

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 04/12/2024**BradenHead**Date of Last Brhd Test: 01/18/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

| Comment   | User           | Date              |
|---|----------------|-------------------|
| <u>ECMC Inspection Report Summary</u><br><u>Inspector Michael Kester,</u><br><u>conducted an on-site Follow up inspection as per doc# 713300693, in accordance with Rule 901a,</u><br><u>corrective actions appeared to have NOT been addressed</u><br><br><u>Location: UPRR 43 Pan Am G 2</u><br><u>Operator: KPK</u><br><u>API#: 123-08087</u><br><u>County: Weld</u><br><br><u>Mechanical integrity Testing, Rule 417b, corrective action date 4-12-2024</u><br><u>Weather conditions: clear and dry</u><br><br><u>This inspection does not nullify any orders or NOAV from the ECMC</u> | <u>kesterm</u> | <u>11/14/2024</u> |

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num     | Description     | URL  |
|------------------|-----------------|--|
| <u>713301254</u> | <u>site pic</u> | <u><a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6795083">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6795083</a></u> |