

Inspection Photos

API: 061-06765

Operator: THOMAS L SPRING LLC

Inspection Date: 11/20/2024

County: KIOWA



Inspection Photos



Photo 1. Facing southwest toward the location which is stabilized with perennial native vegetation.



Inspection Photos



Photo 2. Facing southeast toward the wellsite.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06765 | Date: 11/20/2024

Inspection Photos



Photo 3. There is a slight leak at the tank seam.



Inspection Photos




Photo 4. There are some gaps in the wire mesh that need to be repaired to prevent entry.

