

WELL NAME: AC 12-03, API #: 071-08296, INSP. # 716300261



PHOTO 1: WELL SIGN



PHOTO 2: LOCATION.





PHOTO 3: WELLHEAD AND EQUIPMENT.





PHOTO 4: WELL EQUIPMENT.



WGS84
±15ft

37.10495, -104.94914

ft
±12ft

8404

°M
±10

SE136



Colorado Oil & Gas Conservation commission
© 20-Nov-24 12:00:24

PHOTO 5: AREA OF IMPACTED SOIL NEAR COMPRESSOR. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 11/30/2024.



Colorado Oil & Gas Conservation commission
© 20-Nov-24 12:00:13

PHOTO 6: AREA OF IMPACTED SOIL NEAR COMPRESSOR. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 11/30/2024.



PHOTO 7: OILY WASTE FROM LEAK IN HYDRAULIC MOTOR HAS FILLED SKID AND HAS SPILLED OVER CAUSING IMPACT SOIL SURROUNDING SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE OR TREAT IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. 11/21/2024.