

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/13/2024

Submitted Date:

11/21/2024

Document Number:

708700066**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Kosola, Jason 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, SIMCOE		sjninspections@ikavenergy.co	
Fischer, Alex		alex.fischer@state.co.us	

**General Comment:**

This is an environmental inspection to document spill area. Irrigation ditch present approximately 480 feet east-southeast of well pad.

Form 19 Supplemental requesting closure of this spill is due by February 16, 2025.

See Conditions of Approval on Form 19 Initial Spill report document number 403995816

From Spill Report:

On November 11th, 2024, an unknown volume of produced water release was discovered near a produced water tank on the northeast edge of the Lila Cummins A2/A3/A4 pad. The discovery came when a technician responded to a high-level alarm from the tank and found standing water around the tank. Environmental personnel were contacted and arrived on site. The standing water around the tank, as well as other standing water on site, were field-tested; results showed only liquids around the tank indicated produced water. In addition, technicians isolated onsite equipment to mitigate any further potential impacts. A water truck was dispatched to the site and recovered approximately 10 BBL of standing water around the tank area.

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER

Estimated Spill Volume:

Comment: Produced water spill. Volume unknown at the time of inspection

Corrective Action: Conduct soil and water sampling as appropriate and report results on Form 19 Supplemental. Spill must be closed within 90 days of discovery or Operator shall submit a Form 27 Remediation Plan for approval.

Date: 02/26/2025

Reportable: YES

GPS: Lat 37.137129

Long -107.720094

Proximity to Surface Water: 480

Depth to Ground Water:

Water Well Complaint:

DWR Receipt Num:

Owner Name:

GPS :

Lat

Long

Field Parameters:

Sample Location:

Comment:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708700067	Inspection photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6795486">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6795486</a>
708700068	Map	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6795487">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6795487</a>

Date Run: 11/21/2024 Doc [#708700066]

Page 2 of 2