

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
404004079

Date Received:  
11/22/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Heil, John

john.heil@state.co.us

TEP

COGCCInspectionReports@terraep.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708905072

Inspection Date: 11/21/2024

FIR Submit Date: 11/21/2024

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

#### LOCATION - Location ID: 335236

Location Name: CLOUGH-66S94W Number: 20NWSE County: \_\_\_\_\_

Qtrqtr: NWSE Sec: 20 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.509039 Longitude: -107.909431

#### FACILITY - API Number: 05-045- -00 Facility ID: 335236

Facility Name: CLOUGH-66S94W Number: 20NWSE

Qtrqtr: NWSE Sec: 20 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.509039 Longitude: -107.909431

### CORRECTIVE ACTIONS:

1 CA# 200637

Corrective Action: All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition.

Date: 11/22/2024

Response: CA COMPLETED

Date of Completion: 11/22/2024

Operator Comment: On 11/21/24, TEP responded to a small dump line leak at the Clough RMV 25-20 well pad. The well was shut in for the night, and crews returned this morning (11/22/24) to repair the leak. Production personnel discovered that a union joint was not fully tightened and had leaked approximately 3 gallons of produced water. Repairs were completed by approximately 8:30 a.m. on 11/22/24. Impacted soils were also cleaned up / removed, and the area was repaired with clean gravel (see attached). This was not a reportable incident.

The Field Inspection Report states that the "location is approximately 68 yards from a drainage that contributes to the Colorado River." To clarify, the location may be 68 yards from a dry drainage that is tributary to the Colorado River, however. the actual distance from the location to the Colorado River is approximately 4,300 feet (1,430 yards).

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: The small leak was cleaned up on 11/22/24. This was not a reportable event. The corrective action has been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 11/22/2024 12:04:42 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

404004113	RMV 25-20 cleanup
-----------	-------------------

Total Attach: 1 Files