

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404004079

Date Received:
11/22/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Heil, John		john.heil@state.co.us
.TEP		COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708905072
Inspection Date: 11/21/2024 FIR Submit Date: 11/21/2024 FIR Status:

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335236

Location Name: CLOUGH-66S94W Number: 20NWSE County:
Qtrqr: NWSE Sec: 20 Twp: 6S Range: 94W Meridian: 6
Latitude: 39.509039 Longitude: -107.909431

FACILITY - API Number: 05-045-00 Facility ID: 335236

Facility Name: CLOUGH-66S94W Number: 20NWSE
Qtrqr: NWSE Sec: 20 Twp: 6S Range: 94W Meridian: 6
Latitude: 39.509039 Longitude: -107.909431

CORRECTIVE ACTIONS:

1 CA# 200637

Corrective Action: All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition. Date: 11/22/2024

Response: CA COMPLETED Date of Completion: 11/22/2024

Operator Comment: On 11/21/24, TEP responded to a small dump line leak at the Clough RMV 25-20 well pad. The well was shut in for the night, and crews returned this morning (11/22/24) to repair the leak. Production personnel discovered that a union joint was not fully tightened and had leaked approximately 3 gallons of produced water. Repairs were completed by approximately 8:30 a.m. on 11/22/24. Impacted soils were also cleaned up / removed, and the area was repaired with clean gravel (see attached). This was not a reportable incident.

The Field Inspection Report states that the "location is approximately 68 yards from a drainage that contributes to the Colorado River." To clarify, the location may be 68 yards from a dry drainage that is tributary to the Colorado River, however, the actual distance from the location to the Colorado River is approximately 4,300 feet (1,430 yards).

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The small leak was cleaned up on 11/22/24. This was not a reportable event. The corrective action has been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental Lead

Date: 11/22/2024 12:04:42 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404004079	FIR RESOLUTION SUBMITTED
404004113	RMV 25-20 cleanup

Total Attach: 2 Files