

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/20/2024

Submitted Date:

11/24/2024

Document Number:

708905085

**FIELD INSPECTION FORM**

Loc ID 335175 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

25 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211145	WELL	PR	02/15/1995	GW	045-06904	CLOUGH RMV-10-22	PR
281515	WELL	PR	08/01/2006	GW	045-11477	CLOUGH RWF 322-22	PR
281517	WELL	PR	07/30/2006	GW	045-11478	CLOUGH RWF 422-22	PR
281518	WELL	PR	07/30/2006	GW	045-11479	CLOUGH RWF 522-22	PR
281521	WELL	PR	07/30/2006	GW	045-11480	CLOUGH RWF 32-22	PR

**General Comment:**

[CECMC Inspection Report Summary](#)  
On 11/20/2024 at approximately 13:56 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC CLOUGH RMV 10-22 pad. Location # 335175 in Garfield County Colorado. Location is within High Priority/Density Habitat areas & in close proximity to Bald Eagle Roost Site. While there, I observed normal production operations.

This is a summary of inspection report.

Split pad/remote location - Shared facilities with the CLOUGH RMV 160-22 pad, location # 335069

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:

Type	OTHER		
Comment:	Catalytic heater & methanol tank - hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Catalytic heater		
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	RMV 10-22 & RWF 522-22 wells have Taylor plugs on bradenheads, bradenhead valves are accessible.  Remaining 3 wells have no form of pressure monitoring equipment located on bradenheads, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:	Marked		
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	500 gal	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			

Comment: <a href="#">Separate containment</a>						Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	1	<100 BBLS	STEEL AST		,		
Comment: <a href="#">Tank equipped with telemetry</a>						Date:	
Corrective Action:						Date:	
<b>Paint</b>							
Condition	Adequate						
Other (Content)							
Other (Capacity)	80 bbls						
Other (Type)							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent					
Comment: <a href="#">Centralized containment</a>						Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	1	200 BBLS	STEEL AST		,		
Comment: <a href="#">Tank equipped with telemetry</a>						Date:	
Corrective Action:						Date:	
<b>Paint</b>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent					
Comment: <a href="#">Centralized containment</a>						Date:	
Corrective Action:						Date:	
<b>Venting:</b>							
Yes/No	NO						
Comment:							
Corrective Action:							
						Date:	
<b>Flaring:</b>							
Type							
Comment:							
Corrective Action:							
						Date:	

Inspected Facilities									
Facility ID:	211145	Type:	WELL	API Number:	045-06904	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	281515	Type:	WELL	API Number:	045-11477	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	281517	Type:	WELL	API Number:	045-11478	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	281518	Type:	WELL	API Number:	045-11479	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	281521	Type:	WELL	API Number:	045-11480	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps						
		Ditches				
Berms						
Compaction						Small amount of light compaction
Ditches						
		Rip Rap				
		Culverts				
		Retention Ponds				
Rip Rap						
		Compaction				
		Gravel				Sparse to none in sections
Check Dams						
		Check Dams				
Gravel						Sparse to none in some areas

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Split pad/remote location - Shared facilities with the CLOUGH RMV 160-22 pad, location # 335069</a>	smelserw	11/24/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708905086	Inspection 708905085 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6798903">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6798903</a>
708905087	Inspection 708905085 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6798904">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6798904</a>