

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 66-20 Pad

Location ID: 335272



Photo # 1045 From entrance to location




Photo # 1046 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 66-20 Pad

Location ID: 335272



Photo # 1047 Location



Photo # 1048 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 66-20 Pad

Location ID: 335272



Photo # 1049 Location



Photo # 1050 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 66-20 Pad

Location ID: 335272



Nov 6, 2024 at 11:42:46 AM
CO



Nov 21, 2024 at 3:56:48 PM
CO

Photo # 9420 From inspection 708904982 conducted on
11/06/2024 - Open ended load line

Photo # 1051 Open ended load line