

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/18/2024

Submitted Date:

11/18/2024

Document Number:

717700754**FIELD INSPECTION FORM**Loc ID 454560 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10518Name of Operator: CONFLUENCE DJ LLCAddress: 1401 WYNKOOP STREET STE 120City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**23 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gale, Justin		kgale@confluencelp.com	<a href="#">All Inspections</a>
Rothe, Brittany		brothe@confluencelp.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454555	WELL	PR	02/14/2020	OW	123-46612	70 Ranch 10-18-3L	SI
454556	WELL	PR	02/14/2020	OW	123-46613	70 RANCH 10-16-2L	SI
454557	WELL	PR	01/01/2021	OW	123-46614	70 Ranch 10-5-4L	SI
454558	WELL	PR	02/14/2020	OW	123-46615	70 RANCH 10-17-1L	PR
454561	WELL	PR	01/01/2019	OW	123-46617	70 Ranch 10-8-4L	SI
454563	WELL	PR	11/01/2019	OW	123-46619	70 Ranch 10-8-2L	SI
456635	WELL	PR	02/14/2020	OW	123-47591	70 RANCH 10-13-2L	SI
456636	WELL	PR	01/01/2021	OW	123-47592	70 Ranch 10-4-4L	SI
456637	WELL	PR	02/14/2020	OW	123-47593	70 RANCH 10-14-1L	SI
456638	WELL	PR	02/14/2020	OW	123-47594	70 Ranch 10-15-3L	SI
464788	WELL	PR	02/14/2020	OW	123-50188	70 Ranch 10-12-3L	WK

**General Comment:**[This is an audit on the Location](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Trash in multiple spots needs to be removed for good housekeeping. See attached report		
Corrective Action:	Comply with Rule 606	Date:	12/31/2024
Type	OTHER		
Comment:	Stained Soil in multiple spots needs to be removed. See attached report		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	12/26/2024
Type	OTHER		
Comment:	Oily Waste in multiple spots needs to be removed. See attached report.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	12/31/2024

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Sound Wall around ECD		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sound wall around VRUs		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	#		
Comment:	Unmarked Riser next to the east separators needs to be marked and LO/TO. See attached report.		
Corrective Action:	Comply with the 1100 rules		Date: 12/31/2024
Type: Other	#		
Comment:	Valves around stained soil need to be fixed or replaced. See attached report.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 12/31/2024

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

**Inspected Facilities**Facility ID: 454555 Type: WELL API Number: 123-46612 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI for frack

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 07/28/2024Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454556 Type: WELL API Number: 123-46613 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI for frack

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 07/28/2024Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454557 Type: WELL API Number: 123-46614 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI for frack

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 07/28/2024Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454558 Type: WELL API Number: 123-46615 Status: PR Insp. Status: PR

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI for frack

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454561 Type: WELL API Number: 123-46617 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI for frack

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 07/28/2024Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454563 Type: WELL API Number: 123-46619 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI for frack

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 07/28/2024Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 456635 Type: WELL API Number: 123-47591 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI for frack

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 07/28/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 456636 Type: WELL API Number: 123-47592 Status: PR Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: SI for frack

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 07/28/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 456637 Type: WELL API Number: 123-47593 Status: PR Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: SI for frack

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 07/28/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 456638 Type: WELL API Number: 123-47594 Status: PR Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: SI for frack

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/28/2024

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	464788	Type:	WELL	API Number:	123-50188	Status:	PR	Insp. Status:	WK
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

BradenHead

Date of Last Brhd Test: 07/28/2024

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Workover

Comment:

Rig on well for Frack prep

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
<div>ECMC Inspection Report Summary</div> <div>On Friday, November 15, 2024, at approximately 8:11 AM, Inspector Adam Burns conducted an on-site inspection at the following location:</div> <div>Location: 70 Ranch 10 West</div> <div>Operator: Confluence DJ LLC</div> <div>Location ID # 454560</div> <div>County: Weld</div> <div>During the inspection, a producing well was observed. The following possible compliance issues were identified:</div> <div>Trash in multiple spots needs to be removed for good housekeeping. Comply with Rule 606</div> <div>Oily Waste in multiple spots needs to be removed. "Properly dispose of oily waste in accordance with 905.e."</div> <div>Stained Soil in multiple spots needs to be removed. "Properly dispose of oily waste in accordance with 905.e."</div> <div>Valves around stained soil need to be fixed or replaced. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.</div> <div>Unmarked Riser next to the east separators needs to be marked and LO/TO. Comply with the 1100 rules</div> <div>A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules.</div> <div>Please note that any corrective actions from previous inspections that have not been addressed remain applicable.</div>	burnsa	11/18/2024

Attached Documents

You can go to ECMC Images ([https://ecmc.state.co.us/weblink/](https://ecmc.state.co.us/webblink/)) and search by document number:

Document Num	Description	URL
403997737	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6790434">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6790434</a>
717700755	Inspection Report	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6790406">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6790406</a>

--