

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/14/2024

Submitted Date:

11/18/2024

Document Number:

713400475

FIELD INSPECTION FORM

Loc ID: 335680 Inspector Name: Popejoy, Dusty On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 21 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Toews, Wesley		wtoews@blm.gov	
ENERGY, QB		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
408	WELL	PR	07/01/2017	GW	045-15497	SGU CP12D-23 M23 49	SI

General Comment:

[CECMC Inspection Report Summary](#)

On 11/14/2024 at approximately 14:06 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection at QB ENERGY SGU-64S96W/23SWSW (M23-496) at Location ID #335680 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1. Housekeeping - Loose barbed wire fencing/wildlife hazard with a CA date of 11/25/2024
2. Equipment - Flow line heating insulation open ended/wildlife hazard available for entry by wildlife with a CA date of 11/25/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location			
Lease Road:			
Type	Access		
comment:	Access		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	970-285-2615/911		
Corrective Action:		Date:	
Good Housekeeping:			
Type	OTHER		
Comment:	Loose barbed wire fencing/wildlife hazard		
Corrective Action:	Comply with CECMC wildlife rules		Date: 11/25/2024
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fencing		

Corrective Action:		Date:	
Equipment:			corrective date
Type: Other	# 1		
Comment:	Flow line heating insulation open ended/wildlife hazard available for entry by wildlife		
Corrective Action:	Comply with CECMC wildlife rules	Date:	11/25/2024
Type: Ancillary equipment	# 1		
Comment:	Well heater		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Liquid nitrogen cylinders		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is accessible		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	OTHER	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	250 bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment: Centralized containment					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	HEATED STEEL AST		,
Comment: Tanks equipped with telemetry					
Corrective Action:				Date:	
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity) 250 bbls					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment: Centralized containment					
Corrective Action:				Date:	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 408 Type: WELL API Number: 045-15497 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Shut in at separator

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other						Stockpiled soils on location with dirt berm BMP
Compaction						
		Ditches				
Waddles						
Ditches						
		Waddles				
				Material Handling And Spill Prevention		Chemical tank containments
		Compaction				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Housekeeping and Equipment for corrective actions.	popejoyd	11/18/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403998652	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6791414
713400476	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6791413