



Inspection Photos  
Location Name: Federal 3-11  
Location ID: 322429  
Inspection Date: 11/14/2024

Wellhead and pump jack.

Nov 14, 2024 12:46:55 PM  
+39.3816N -108.9639W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Federal 3-11  
Location ID: 322429  
Inspection Date: 11/14/2024

Location of the active gas leak originating from the wellhead.

Nov 14, 2024 12:47:01 PM  
+39.3816N -108.9639W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Federal 3-11  
Location ID: 322429  
Inspection Date: 11/14/2024

Location of the active gas leak originating from the wellhead.

Nov 14, 2024 12:47:06 PM  
+39.3816N -108.9639W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Federal 3-11  
Location ID: 322429  
Inspection Date: 11/14/2024

Wellhead sign.



**FOUNDATION**  
ENERGY MANAGEMENT, LLC

24 HR Emergency # (866) 767-3600  
In Case of Emergency Call 911  
OGL# 322429  
Federal 3-11-8-104  
Garfield County, CO  
API# 05-045-06237  
Lease# COC12698  
NWSW 11 8S 104 6PM  
Nearest Access Road: County 201

Nov 14, 2024 12:46:08 PM

+39-3817N -108.9639W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Federal 3-11  
Location ID: 322429  
Inspection Date: 11/14/2024

95 bbl produced water  
steel AST.

Nov 14, 2024 12:48:14 PM  
+39.3817N -108.9638W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Federal 3-11  
Location ID: 322429  
Inspection Date: 11/14/2024

95 bbl produced water  
steel AST, inadequate  
secondary containment  
structure.

Nov 14, 2024 12:48:26 PM  
+39.3816N -108.9637W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Federal 3-11  
Location ID: 322429  
Inspection Date: 11/14/2024

95 bbl produced water  
steel AST, inadequate  
secondary containment  
structure.

Nov 14, 2024 12:48:06 PM  
+39.3817N -108.9638W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Federal 3-11  
Location ID: 322429  
Inspection Date: 11/14/2024

Flowlines or crude oil transfer lines not maintained to prevent failures. Valves not locked and tagged out.

Nov 14, 2024 12:49:02 PM  
+39.3815N -108.9640W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Federal 3-11  
Location ID: 322429  
Inspection Date: 11/14/2024

Flowlines or crude oil transfer lines not maintained to prevent failures. Valves not locked and tagged out.

Nov 14, 2024 12:49:32 PM  
+39.3816N -108.9642W



Inspection Photos  
Location Name: Federal 3-11  
Location ID: 322429  
Inspection Date: 11/14/2024

Earthen produced water  
pit.

Nov 14, 2024 12:49:40 PM  
+39.3816N -108.9642W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources