

Inspection Photos

November 1st, 2024

Operator: Petrox Resources Inc. - 69805

Location ID: 378718

Inspection Document #: 714001431

Archuleta County, CO

Township: SESW 16 33N 5W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Wright 33-5 16-1
Location ID: 378718



Photo 1. View of the well disturbance taken from the access point facing center. Local emergency # missing from well signage.



API #: 067-06277

Inspection Photos
Location Name: Wright 33-5 16-1
Location ID: 378718



Photo 2. Gravel in produced water tank secondary containment which is affecting overall capacity/volume.

Inspection Photos
Location Name: Wright 33-5 16-1
Location ID: 378718



Photo 3. View of western and eastern portions of the pad which have not been interim reclaimed to 1003 standards/requirements.

Inspection Photos
Location Name: Wright 33-5 16-1
Location ID: 378718



Photo 4. 2024 aerial imagery of areas on well pad which have not been reclaimed per 1003 requirements/standards.

Inspection Photos
Location Name: Wright 33-5 16-1
Location ID: 378718



Photo 5. Reference area composed of Juniper, Gambel Oak and Indian Ricegrass.