

# Inspection Photos

November 20th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 443138

Inspection Document #: 714001544

La Plata County, CO

Township: SESE 5 32N 6W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Anderson 3-5H  
Location ID: 443138

November 20, 2024 at 11:08:05 AM MST  
19° N



**Photo 1.** View of the well disturbance taken from the access point facing center.

Inspection Photos  
Location Name: Anderson 3-5H  
Location ID: 443138



**Photo 2.** View of weedy Russian Thistle Debris and Kochia observed on the active pad and within southern fill slope area.

Inspection Photos  
Location Name: Anderson 3-5H  
Location ID: 443138

November 20, 2024 at 11:11:35 AM MST  
355° N



**Photo 3.** View of northern fill slope that remains with mostly bare soils and minimal vegetation.

Inspection Photos  
Location Name: Anderson 3-5H  
Location ID: 443138



**Photo 4.** 2024 aerial imagery of areas on well pad which have not been reclaimed per 1003 requirements/standards. Areas no longer needed for operations highlighted in red have not been interim reclaimed.

API #: 067-09948



November 20, 2024 at 11:17:47 AM MST  
259° W



**Photo 5.** Weedy Russian Thistle and Kochia debris observed dominating the access road.

Inspection Photos  
Location Name: Anderson 3-5H  
Location ID: 443138



Photo 6. View of closed gates leaving location.

Inspection Photos  
Location Name: Anderson 3-5H  
Location ID: 443138



**Photo 5** Reference area composed of Juniper, Gambel Oak and Indian Ricegrass.