

Caerus  
School House Point OM L15  
Location ID: 335979



Location



Location

Caerus  
School House Point OM L15  
Location ID: 335979



Location



Location

Caerus  
School House Point OM L15  
Location ID: 335979



Condensate tank venting



Well signage needs maintained

Caerus  
School House Point OM L15  
Location ID: 335979



Well signage needs maintained



Signage is beginning to become illegible

Caerus  
School House Point OM L15  
Location ID: 335979




No meter noticed



Open manway on tank

Caerus  
School House Point OM L15  
Location ID: 335979



Open manway on tank



Debris

Caerus  
School House Point OM L15  
Location ID: 335979



Debris



Debris

Caerus  
School House Point OM L15  
Location ID: 335979



Debris



Debris

Caerus  
School House Point OM L15  
Location ID: 335979



**Barbed wire is debris and a wild life hazard**



**Barbed wire is debris and a wild life hazard**

Caerus  
School House Point OM L15  
Location ID: 335979



Debris



Debris

Caerus  
School House Point OM L15  
Location ID: 335979



Barbed wire is debris and a wild life hazard



Cut slope shows some signs of lack of stablization