

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2024

Submitted Date:

11/19/2024

Document Number:

707801231

FIELD INSPECTION FORMLoc ID 335582 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265297	WELL	PR	08/01/2024	GW	045-08997	CHEVRON 22-8D	PR
265298	WELL	PR	08/01/2024	GW	045-08996	CHEVRON 12-8D	PR
284336	WELL	PR	08/01/2024	GW	045-12145	CHEVRON 1B-8D	PR
284340	WELL	PR	08/01/2024	GW	045-12144	CHEVRON 1D-8D	PR
284341	WELL	PR	08/01/2024	GW	045-12143	CHEVRON 1F-8D	PR
284342	WELL	PR	08/01/2024	GW	045-12142	CHEVRON 2B-8D	PR
284343	WELL	PR	08/01/2024	GW	045-12141	CHEVRON 1C-8D	PR

General Comment:**ECMC Inspection Report Summary**

On Friday 11/15/2024, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus Chevron 66S96W 8SWNW, at Location # 335582 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Location shows signs of lack of stabilization/ compaction and no evidence of tracking controls.

2. Stored equipment

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Stored equipment (loader)		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Bradenhead	# 7		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	265297	Type:	WELL	API Number: 045-08997 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	265298	Type:	WELL	API Number: 045-08996 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	284336	Type:	WELL	API Number: 045-12145 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	284340	Type:	WELL	API Number: 045-12144 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	284341	Type:	WELL	API Number: 045-12143 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	284342	Type:	WELL	API Number: 045-12142 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	284343	Type:	WELL	API Number: 045-12141 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Sediment Traps				
		Retention Ponds				
Gravel						Sparse to none
Compaction						Light compaction in areas
Berms						
		Ditches				

Comment: Location shows signs of lack of stabilization/ compaction and no evidence of tracking controls. Maintenance relative to storm water runoff, operators shall consider seasonal factors, such as winter snow cover and spring runoff from snowmelt, to ensure site conditions and controls are adequate and in place to effectively manage storm water. Places with sparse to no gravel & light compaction are present on location. Sparse to no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action: Install, maintain or repair required BMPs

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403999901	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6792553
707801236	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6792520