

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/14/2024

Submitted Date:

11/19/2024

Document Number:

708905060

FIELD INSPECTION FORM

Loc ID: 323868 Inspector Name: Smelser, Wayne On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635

Findings:

25 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211045	WELL	PR	12/01/2017	GW	045-06803	JUHAN 14-26H	PR

General Comment:

[CECMC Inspection Report Summary](#)
 On 11/14/2024 at approximately 12:00 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC JUHAN 14-26H Pad. Location # 323868 in Garfield County Colorado.
 Please refer to inspection 708904679 conducted on 09/25/2024, previous corrective action has been completed.
 Location is within High Priority/Density/NSO/Black Bear Habitat areas.
 Location is approximately 24 yards from Porcupine Creek.
 While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- Housekeeping - Stored stockpile on location with a CA date of 12/19/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
 This is a summary of inspection report.

Any corrective actions from previous inspections that have not been addressed are still applicable.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	<p>Stored stockpile on location - stockpiled soils & gravel. Additionally the stockpile is also interfering with interim reclamation & lacks Stormwater BMP's as well.</p> <p>On November 12th 2024 Environmental Protection Specialist John Heil emailed TEP to try & get some more information about the stockpiled materials & was informed that the stockpiled materials were left over after the former pit at this location was closed/reclaimed & that it no longer belongs to TEP but instead belongs to the landowner.</p>		
Corrective Action:	The storage, placement, or maintenance of equipment, vehicles, trailers, commercial products, Chemicals, drums, totes, Containers, materials, and all other supplies not necessary for use on an Oil and Gas Locations is prohibited.		Date: 12/19/2024
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		

Comment:	Methanol tank - hog panels		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:	Hog panels		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Taylor plug located on bradenhead, bradenhead valve is accessible		
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	ECD does not appear to be in FORM 2A or FORM 4/not in compliance with CECMC rules		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream Meter does not appear to be in FORM 2A or FORM 4/not in compliance with CECMC rules		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS

METHANOL	1	<50 BBLs	STEEL AST		
Comment: Tank does not appear to be in FORM 2A or FORM 4/not in compliance with CECMC rules					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity) 500 gal					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
Comment: Separate containment					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		
Comment: Tank equipped with telemetry					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity) 80 bbl					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate				
Comment: Separate containment					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 211045 Type: WELL API Number: 045-06803 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Spill Response		Spill response station
		Compaction				
Gravel						Sparse to none in areas
Compaction						Small amount of light compaction
		Gravel				Sparse to none in sections
Other	Fail					Stockpiled soils on location with no BMPs
		Ditches				
		Culverts				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>Please refer to Housekeeping for corrective action & also refer to Equipment, Tanks & Berms & Stormwater for comments.</p> <p>Any corrective actions from previous inspections that have not been addressed are still applicable.</p>	smelserw	11/19/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404000252	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6792997
708905061	Inspection 708905060 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6792995
708905062	Inspection 708905060 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6792996