

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/22/2024

Submitted Date:

11/22/2024

Document Number:

713301325

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 318144 _____ Kester, Michael _____ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: _____ 46290 _____
 Name of Operator: KP KAUFFMAN COMPANY INC _____
 Address: 1700 LINCOLN ST STE 4550 _____
 City: _____ DENVER _____ State: _____ CO _____ Zip: _____ 80203 _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 _____ Number of Comments
 1 _____ Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|--------------|---------------------------|-----------------|
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| , KPK | 303-825-4822 | cogcc@kpk.com | all inspections |
| Silver, Randy | 720-827-6688 | randy.silver@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 240703 | WELL | SI | 05/01/2021 | OW | 123-08491 | PELTIER UNIT B 1 | SI |

General Comment:

follow up inspection

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | good | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | | Date: | |
| Corrective Action: | | | |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|-----------------------------------|-------|--|
| Type | OTHER | | |
| Comment: | electric disconnect, metal panels | | |
| Corrective Action: | | Date: | |
| Type | PUMP JACK | | |
| Comment: | safety guards | | |
| Corrective Action: | | Date: | |

Equipment:

| Type | Quantity | Comment | Corrective Action | Date | corrective date |
|---------------------|----------|----------------------------|-------------------|------|-----------------|
| Prime Mover | # 1 | electric | | | |
| Pump Jack | # 1 | | | | |
| Ancillary equipment | # 3 | electric/automation panels | | | |
| Bradenhead | # 1 | piped to surface | | | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 240703 Type: WELL API Number: 123-08491 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTED

Comment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Valves appeared to be closed at time of inspection

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 04/29/2024

BradenHead

Date of Last Brhd Test: 02/01/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|---|---------|------------|
| <p>ECMC Inspection Report Summary Inspector Michael Kester, conducted an on-site Follow up inspection as per doc# 713300767 in accordance with Rule 901a, corrective actions appeared to have NOT been addressed</p> <p>Location: Peltier Unit B 1 Operator: KPK API#: 123-08491 County: Weld</p> <p>Mechanical integrity Testing, Rule 417b, corrective action date 4-29-2024 Weather conditions: clear and dry</p> <p>This inspection does not nullify any orders or NOAV from the ECMC</p> | kesterm | 11/22/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 713301326 | site pic | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6801283 |