

Inspection Photos

Loc: 324494

Operator: **OXY USA INC**

Inspection Date: 11/25/2024

County: Huerfano



Inspection Photos



Photo 1. Facing south toward the access road.. The access road will need to be decompacted and reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324494 | Date: 11/25/2024

Inspection Photos



Photo 2. Facing south toward the location. The location is currently being recontoured.



Inspection Photos



Photo 3. Facing southwest at the location. There appears to be more material in this area that needs to be pushed up toward the cu slope.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324494 | Date: 11/25/2024

Inspection Photos



Photo 4. There is still a pipeline riser that remains at enter of the location that needs to be removed per the Rules.



Inspection Photos



Photo 5. Facing southeast at the location. This area appears to need more material to match surrounding contours. Recontouring is still in process.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324494 | Date: 11/25/2024

Inspection Photos



Photo 6. There is an electrical box at the northeast corner of the location that must be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324494 | Date: 11/25/2024