

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2024

Submitted Date:

11/26/2024

Document Number:

699700446

FIELD INSPECTION FORMLoc ID 323939 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 51130

Name of Operator: LOCIN OIL CORPORATION

Address: 600 TRAVIS STREET SUITE 5050

City: HOUSTON State: TX Zip: 77002

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Burn, Diana		diana.burn@state.co.us	
Schultz, Scott		Scott.Schultz@coag.gov	CO AG
Frost, Joe	7137423642	jfrost@americanhelium.us	American Helium President
Schroeder, Siera	7197231542	siera.schroeder@state.co.us	Enforcement Advisor
Katz, Aaron		aaron.katz@state.co.us	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Roberts, James		j75rober@blm.gov	BLM meeker

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
119497	PIT	CL			-	Bridle Federal #44-2 119497	EI
211311	WELL	SI	06/01/2020	GW	045-07070	BRIDLE FEDERAL 44-2	EI

General Comment:

ECMC Environmental Inspection. Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Location					
Overall Good: <input type="checkbox"/>					
Emergency Contact Number:					
Comment:				Date: _____	
Corrective Action:					
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:				corrective date	
Type: Other	#				
Comment:		Active gas leak originating at the wellhead. See email notification Doc #2573189 for more information.			
Corrective Action:		Locin shall securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date:	
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	119497	Type:	PIT	API Number:	-	Status:	CL	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	211311	Type:	WELL	API Number:	045-07070	Status:	SI	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700447	20241114 Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6802089