

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2024

Submitted Date:

11/25/2024

Document Number:

717000169

FIELD INSPECTION FORMLoc ID 450043 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10459

Name of Operator: EXTRACTION OIL & GAS INC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@extracti onog.com	All Inspectors

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450045	WELL	PR	04/01/2023	OW	001-10032	PC 1S-66-2928 12NH	PR
450046	WELL	PR	04/01/2023	OW	001-10033	PC 1S-66-2928 3NH	PR
450047	WELL	PR	04/01/2023	OW	001-10034	PC 1S-66-2928 17NH	PR
450052	WELL	PR	04/01/2023	OW	001-10039	PC 1S-66-2928 20CDH	PR
450053	WELL	PR	04/01/2023	OW	001-10040	PC 1S-66-2928 2CDH	PR
450054	WELL	PR	04/01/2023	OW	001-10041	PC 1S-66-2928 7CDH	PR
450055	WELL	PR	04/01/2023	OW	001-10042	PC 1S-66-2928 14CDH	PR
450056	WELL	PR	04/01/2023	OW	001-10043	PC 1S-66-2928 9NH	PR
450057	WELL	PR	04/01/2023	OW	001-10044	PC 1S-66-2928 19NH	PR
450058	WELL	PR	09/01/2023	OW	001-10045	PC 1S-66-2928 5NH	PR
450059	WELL	PR	04/01/2023	OW	001-10046	PC 1S-66-2928 8NH	PR

General Comment:

Routine inspection

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:		Adequate			
Corrective Action:					Date: _____
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:		corrective date			
Type: Ancillary equipment	# 1				
Comment:					
Corrective Action:		Date:			
Type: Emission Control Device	# 6				
Comment:					
Corrective Action:		Date:			
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:		Date:			
Type: Compressor	# 1				
Comment:					
Corrective Action:		Date:			
Type: Bird Protectors	# 15				
Comment:					
Corrective Action:		Date:			
Type: Plunger Lift	# 11				
Comment:					
Corrective Action:		Date:			
Type: Vertical Heater Treater	# 1				
Comment:					
Corrective Action:		Date:			
Type: Horizontal Heated Separator	# 10				
Comment:					
Corrective Action:		Date:			
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		,

Comment:							
Corrective Action:						Date:	

Paint

Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

Berms

Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance	
Metal	Adequate	Walls Sufficent		Base Sufficent		Adequate	
Comment:							
Corrective Action:						Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	9	400 BBLs	STEEL AST		39.934931,-104.804228		
Comment:							
Corrective Action:						Date:	

Paint

Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

Berms

Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance	
Metal	Adequate	Walls Sufficent		Base Sufficent		Adequate	
Comment:							
Corrective Action:						Date:	

Wells Served By Facilities Above

AirsID

API Number	API Number	AirsID
001-10039		
001-10032		
001-10034		
001-10033		
001-10040		
001-10044		
001-10042		
001-10043		
001-10041		
001-10045		
001-10046		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	450045	Type:	WELL	API Number:	001-10032	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	450046	Type:	WELL	API Number:	001-10033	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	450047	Type:	WELL	API Number:	001-10034	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	450052	Type:	WELL	API Number:	001-10039	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	450053	Type:	WELL	API Number:	001-10040	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	450054	Type:	WELL	API Number:	001-10041	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	450055	Type:	WELL	API Number:	001-10042	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	450056	Type:	WELL	API Number:	001-10043	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	450057	Type:	WELL	API Number:	001-10044	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	450058	Type:	WELL	API Number:	001-10045	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	450059	Type:	WELL	API Number:	001-10046	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
BradenHead									
Date of Last Brhd Test:	04/17/2024		Annual Brhd Completed?						
Last Brhd Test Results	Initial Surf Csg Pressure:		2		Fluid Type:				
	End Surf Csg Pressure:		0						
Comment:	Appeared to be plumbed to the surface								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
ECMC Comments									

Comment	User	Date
Routine inspection	finkenbc	11/25/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717000170	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6802095