

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/13/2024

Submitted Date:

11/26/2024

Document Number:

701104100

FIELD INSPECTION FORMLoc ID 311649 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	All engineering

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284981	WELL	PR	02/01/2014	GW	045-12334	N.PARACHUTE WF 13D K25 596	EG
284982	WELL	PR	07/01/2024	GW	045-12331	N.PARACHUTE WF01C K25 596	EG
284983	WELL	PR	06/07/2008	GW	045-12333	N.PARACHUTE WF 14C K25 596	EG
284984	WELL	PR	03/29/2007	GW	045-12332	N.PARACHUTE WF03A K25 596	EG
284985	WELL	PR	01/27/2014	GW	045-12330	N.PARACHUTE WF 04A K25 596	EG
284986	WELL	PR	07/04/2008	GW	045-12329	N.PARACHUTE WF 14B K25 596	EG
284987	WELL	PR	03/29/2007	GW	045-12328	N.PARACHUTE WF05B K25 596	EG
284988	WELL	PR	03/20/2008	GW	045-12327	N.PARACHUTE WF01B K25 596	EG
291477	WELL	SI	05/01/2024	GW	045-14398	N. PARACHUTE WF16D K25596	EG
291478	WELL	PR	07/20/2007	GW	045-14399	N.PARACHUTE WF13B K25 596	EG
291533	WELL	PR	07/23/2007	GW	045-14431	N. PARACHUTE WF13C K25 596	EG
291534	WELL	PR	07/23/2007	GW	045-14430	N.PARACHUTE WF14A K25 596	EG
291535	WELL	PR	07/23/2007	GW	045-14429	N. PARACHUTE WF04C K25 596	EG

291536	WELL	PR	05/01/2023	GW	045-14438	N. PARACHUTE WF04BK25596	EG
291537	WELL	SI	05/01/2024	GW	045-14437	N. PARACHUTE WF05AK25596	EG
291538	WELL	PR	02/01/2022	GW	045-14436	N. PARACHUTE WF01A K25 596	EG
291539	WELL	PR	07/24/2007	GW	045-14432	N. PARACHUTE WF13A K25 596	EG
291540	WELL	PR	07/24/2007	GW	045-14433	N. PARACHUTE WF16C K25 596	EG
291541	WELL	PR	08/01/2019	GW	045-14434	N. PARACHUTE WF16BK25596	EG
291542	WELL	SI	10/01/2021	GW	045-14435	N. PARACHUTE WF16AK25596	EG

General Comment:
[Flowline Integrity Inspection](#)
[Spill/Release N Parachute WF13C well Flowline Facility # 488463](#)

Inspected Facilities					
Facility ID: 284981	Type: WELL	API Number: 045-12334	Status: PR	Insp. Status: EG	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 284982	Type: WELL	API Number: 045-12331	Status: PR	Insp. Status: EG	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 284983	Type: WELL	API Number: 045-12333	Status: PR	Insp. Status: EG	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 284984	Type: WELL	API Number: 045-12332	Status: PR	Insp. Status: EG	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 284985	Type: WELL	API Number: 045-12330	Status: PR	Insp. Status: EG	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 284986	Type: WELL	API Number: 045-12329	Status: PR	Insp. Status: EG	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 284987	Type: WELL	API Number: 045-12328	Status: PR	Insp. Status: EG	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 284988	Type: WELL	API Number: 045-12327	Status: PR	Insp. Status: EG	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 291477	Type: WELL	API Number: 045-14398	Status: SI	Insp. Status: EG	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 291478	Type: WELL	API Number: 045-14399	Status: PR	Insp. Status: EG	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 291533	Type: WELL	API Number: 045-14431	Status: PR	Insp. Status: EG	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 291534	Type: WELL	API Number: 045-14430	Status: PR	Insp. Status: EG	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 291535	Type: WELL	API Number: 045-14429	Status: PR	Insp. Status: EG	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 291536	Type: WELL	API Number: 045-14438	Status: PR	Insp. Status: EG	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 291537	Type: WELL	API Number: 045-14437	Status: SI	Insp. Status: EG	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 291538	Type: WELL	API Number: 045-14436	Status: PR	Insp. Status: EG	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					

Facility ID:	291539	Type:	WELL	API Number:	045-14432	Status:	PR	Insp. Status:	EG
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	291540	Type:	WELL	API Number:	045-14433	Status:	PR	Insp. Status:	EG
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	291541	Type:	WELL	API Number:	045-14434	Status:	PR	Insp. Status:	EG
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	291542	Type:	WELL	API Number:	045-14435	Status:	SI	Insp. Status:	EG
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104101	Flowline integrity inspection 701104100 photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6802790