

Inspection Photos

Location: LARAMIE ENERGY LLC Ed Koch/7-9 Pad

Location ID: 312638

Date: 11/21/2024



Photo # 9673 Entrance to location



Photo # 9703 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Ed Koch/7-9 Pad

Location ID: 312638

Date: 11/21/2024



Photo # 9674 Location



Photo # 9681 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Ed Koch/7-9 Pad

Location ID: 312638

Date: 11/21/2024



Photo # 9702 Location



Photo # 9710 NE corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Ed Koch/7-9 Pad

Location ID: 312638

Date: 11/21/2024



Photo # 9711 SE corner of location



Photo # 9712 SW corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Ed Koch/7-9 Pad

Location ID: 312638

Date: 11/21/2024



Nov 21, 2024 at 3:06:59 PM
+39.286091,-108.254218 ±4.73m
De Beque

Photo # 9713 NW corner of location



Nov 21, 2024 at 2:52:46 PM
+39.285694,-108.254239 ±4.73m
De Beque

Photo # 9698 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location: LARAMIE ENERGY LLC Ed Koch/7-9 Pad

Location ID: 312638

Date: 11/21/2024



Photo # 9704 Tank labels have conflicting capacity information




Photo # 9705 Tank labels have conflicting capacity information

Inspection Photos

Location: LARAMIE ENERGY LLC Ed Koch/7-9 Pad

Location ID: 312638

Date: 11/21/2024



Photo # 9709 Debris

