

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 33-20 Pad

Location ID: 335136



Photo # 1345 From entrance to location




Photo # 1346 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 33-20 Pad

Location ID: 335136



Nov 26, 2024 at 10:41:08 AM
CO

Photo # 1347 Location



Nov 26, 2024 at 10:43:05 AM
CO

Photo # 1348 Mechanical Condition - possible bradenhead leak on the RMV 33-20 well

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 33-20 Pad

Location ID: 335136



Photo # 1349 Mechanical Condition - possible bradenhead leak on the RMV 33-20 well



Photo # 1350 Mechanical Condition - possible bradenhead leak on the RMV 33-20 well

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 33-20 Pad

Location ID: 335136



Photo # 1351 Mechanical Condition - possible bradenhead leak on the RMV 33-20 well