

Western Operating Propst B #2 NESE Sec 27 11 N 53W Photo Log

Access Road Graded fixed storm water erosion



Access Road Graded looking from Gate towards Propst B – 2 Well



Access Road Graded looking towards entrance gate



Straw Wattles re-installed South of old Separator Area, trenched and backfilled



Straw Wattles South of old Separator Area, trenched and backfilled



Straw Wattles South of old Separator Area, trenched and backfilled



Straw Wattles installed South of old Separator Area, Standing South of wattles looking North



Noxious Weeds removed from excavation area and ripped for storm water erosion



Area South of Pumping jack, Storm water erosion fixed and Straw Wattles installed, trenched and backfilled



Straw Wattles installed South of Pump Jack, trenched and backfilled



Straw Wattles installed South of Pump Jack looking from the South to the North



Straw Wattles installed and Storm water erosion fixed



Looking from Southeast corner to the West across excavation



Southeast corner of excavation looking North



East side of excavation looking South, Weeds removed and area ripped for storm water erosion



Scraped up soil from potential impacted area West of the excavation with a berm and signage



West end of excavation, weeds removed and ripped for storm water erosion



West end of excavation, standing on West end looking East. All trash and debris removed



Northwest end of excavation. Perimeter berm has been improved and track packed



Silt fence has been installed for containment from sediment transporting into natural drainage gully



West part of excavation looking East



Soil scraped up from potential impacted area on South end of excavation with a berm and signage



Well Head area



Pump Jack engine room area



Straw Wattles installed on North end of excavation, trenched and backfilled



Straw Wattles installed on North end of excavation

