

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 33-20 Pad

Location ID: 335136



Photo # 1602 From entrance to location



Photo # 1603 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 33-20 Pad

Location ID: 335136



Photo # 1604 Location



Photo # 1605 Mechanical Condition - possible bradenhead leak on the RMV 33-20 well

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 33-20 Pad

Location ID: 335136



**Photo # 1606 Mechanical Condition - possible bradenhead leak on the RMV 33-20 well**



**Photo # 1607 Mechanical Condition - possible bradenhead leak on the RMV 33-20 well**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 33-20 Pad

Location ID: 335136



**Photo # 1608 Mechanical Condition - possible bradenhead leak on the RMV 33-20 well**