

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: PRONGHORN-65N61W 8SWSW

Loc ID: 305849

Inspection: 708201749





CA: This location does not comply with Rule 1004. It does not appear that the former location or access road has been recontoured or graded to match the existing grade/topography. Additional reclamation work is required to restore grade at the disturbance area. Refer to attached inspection photos. Comply with Rule 1004. Recontour/grade and reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

CA Resolution: Operator has reported that the location has been recontoured and areas of disturbance have been reseeded to comply with Rule 1004. Operator will continue to monitor and manage the location to stay in compliance with reclamation activities.