

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 3-20 Pad

Location ID: 323886



Photo # 484 From entrance to location



Photo # 485 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 3-20 Pad

Location ID: 323886



Nov 20, 2024 at 3:07:03 PM
CO



Nov 20, 2024 at 3:05:52 PM
CO

Photo # 486 Location

Photo # 487 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 3-20 Pad

Location ID: 323886



Photo # 488 Location



Photo # 489 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 3-20 Pad

Location ID: 323886



Photo # 9090 From inspection 708904991 conducted on 11/06/2024 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 490 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 3-20 Pad

Location ID: 323886



Photo # 9091 From inspection 708904991 conducted on 11/06/2024 PRV vent line does not comply with CECMC pressure safety device rules

Photo # 491 PRV vent line does not comply with CECMC pressure safety device rules