

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2024

Submitted Date:

11/19/2024

Document Number:

699506621**FIELD INSPECTION FORM**Loc ID 453711 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453704	WELL	PR	09/01/2022	OW	123-46259	QUARTER CIRCLE 24-11HZ	PR
453705	WELL	PR	11/01/2018	OW	123-46260	QUARTER CIRCLE 24-8HZ	PR
453706	WELL	PR	11/01/2021	OW	123-46261	QUARTER CIRCLE 24-10HZ	PR
453707	WELL	SI	04/01/2024	OW	123-46262	QUARTER CIRCLE 24-9HZ	SI
453708	WELL	PR	12/16/2018	OW	123-46263	QUARTER CIRCLE 24-6HZ	PR
453714	WELL	PR	11/01/2021	OW	123-46268	QUARTER CIRCLE 24-7HZ	PR

General Comment:[There have been no changes to equipment on location since previous inspection.](#)

Location				
Overall Good: <input checked="" type="checkbox"/>				
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:			Date:	
Flaring:				
Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities

Facility ID: 453704 Type: WELL API Number: 123-46259 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 08/13/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 23 Fluid Type: NoneEnd Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453705 Type: WELL API Number: 123-46260 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453706 Type: WELL API Number: 123-46261 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453707 Type: WELL API Number: 123-46262 Status: SI Insp. Status: SI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453708 Type: WELL API Number: 123-46263 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453714 Type: WELL API Number: 123-46268 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment

User

Date

At time of inspection location appears to be in compliance with ECMC rules.
At time of inspection weather conditions were windy, cold, clear.

medinaj

11/19/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506622	inspection pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6806655