

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/19/2024

Submitted Date:

11/19/2024

Document Number:

699506625

FIELD INSPECTION FORM

Loc ID 444280 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444275	WELL	PR	07/01/2023	OW	123-42537	MEESE 1C-14HZ	PR
444276	WELL	PR	08/01/2023	OW	123-42538	MEESE STATE 38C-35HZ	PR
444277	WELL	PR	12/01/2023	OW	123-42539	MEESE 37C-35HZ	PR
444278	WELL	PR	07/01/2023	OW	123-42540	MEESE 16N-35HZ	PR
444279	WELL	PR	07/01/2023	OW	123-42541	MEESE 26N-14HZ	PR
444281	WELL	PR	07/01/2023	OW	123-42542	MEESE 1N-14HZ	PR
444282	WELL	PR	08/03/2017	OW	123-42543	MEESE 27N-14HZ	PR
444283	WELL	PR	07/01/2023	OW	123-42544	MEESE STATE 38N-35HZ	PR

General Comment:

There have been no changes to equipment on location since previous inspection.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 444275 Type: WELL API Number: 123-42537 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444276 Type: WELL API Number: 123-42538 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444277 Type: WELL API Number: 123-42539 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444278 Type: WELL API Number: 123-42540 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444279 Type: WELL API Number: 123-42541 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444281 Type: WELL API Number: 123-42542 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444282 Type: WELL API Number: 123-42543 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444283 Type: WELL API Number: 123-42544 Status: PR Insp. Status: PR

Producing Well

Comment: <u>PR</u>	
Corrective Action:	Date:

BradenHead

Date of Last Brhd Test: 08/13/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were windy, cold, clear.	medinaj	11/19/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506626	inspection pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6806657