

## Inspection Photos

Location: LARAMIE ENERGY LLC Woods Spangler/15-13 Pad

Location ID: 334499

Date: 11/25/2024



Photo # 9856 Entrance to location



Photo # 9885 Location

## Inspection Photos

Location: LARAMIE ENERGY LLC Woods Spangler/15-13 Pad

Location ID: 334499

Date: 11/25/2024



Nov 25, 2024 at 1:39:13 PM  
+39.270156,-107.877973 ±4.74m  
Collbran

Photo # 9857 Location



Nov 25, 2024 at 1:55:34 PM  
+39.269902,-107.877653 ±4.73m  
Collbran

Photo # 9871 Location



## Inspection Photos

Location: LARAMIE ENERGY LLC Woods Spangler/15-13 Pad

Location ID: 334499

Date: 11/25/2024



Photo # 9882 Location



Photo # 9905 SE corner of location

## Inspection Photos

Location: LARAMIE ENERGY LLC Woods Spangler/15-13 Pad

Location ID: 334499

Date: 11/25/2024



Photo # 9906 NE corner of location



Photo # 9907 NW corner of location



## Inspection Photos

Location: LARAMIE ENERGY LLC Woods Spangler/15-13 Pad

Location ID: 334499

Date: 11/25/2024



Nov 25, 2024 at 2:33:21 PM  
+39.269632,-107.878350 ±4.73m  
Collbran

Photo # 9908 SW corner of location



Nov 25, 2024 at 1:59:05 PM  
+39.269933,-107.877563 ±4.74m  
Collbran

Photo # 9876 PRV vent line does not comply with CECMC pressure safety device rules

## Inspection Photos

Location: LARAMIE ENERGY LLC Woods Spangler/15-13 Pad

Location ID: 334499

Date: 11/25/2024




Photo # 9893 Replace labels as labels come off