

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2024

Submitted Date:

11/25/2024

Document Number:

699700438**FIELD INSPECTION FORM**Loc ID 322496 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 51130Name of Operator: LOCIN OIL CORPORATIONAddress: 600 TRAVIS STREET SUITE 5050City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schroeder, Siera		siera.schroeder@state.co.us	Enforcement Advisor
Schultz, Scott		Scott.Schultz@coag.gov	CO AG
Burn, Diana		diana.burn@state.co.us	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Roberts, James		j75rober@blm.gov	BLM meeker
Katz, Aaron		aaron.katz@state.co.us	
Frost, Joe		jfrost@americanhelium.us	American Helium President
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210635	WELL	SI	06/01/2020	GW	045-06391	FEDERAL 3-10-84	EI

General Comment:[ECMC Environmental Inspection. Any corrective action\(s\) from previous inspections that have not been addressed are still applicable.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

#

Comment: **Rusted out separator.**Corrective Action: **Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.**Date:

Type: Other

#

Comment: **Active gas leaks originating at the wellhead. See email notification Doc #2573189 for more information.**Corrective Action: **Locin shall securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.**Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER		<50 BBLS	PLASTIC AST		,	
Comment: <input type="text"/>						
Corrective Action: <input type="text"/>						Date: <input type="text"/>

PaintCondition: Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment: Secondary containment structure is absent around the 12 bbl Produced Water Plastic AST.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1).				Date: <input type="text"/>

Venting:Yes/No Comment:

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

