

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/21/2024

Submitted Date:

11/22/2024

Document Number:

707801240**FIELD INSPECTION FORM**Loc ID 335979 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**19 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293404	WELL	PR	01/13/2012	GW	045-14964	SCHOOL HOUSE POINT OM 13A L15 696	PR
293405	WELL	PR	10/24/2013	GW	045-14965	SCHOOL HOUSE POINT OM 12C L15 696	PR
293406	WELL	PR	01/13/2012	GW	045-14966	SCHOOL HOUSE POINT OM 11C L15 696	PR
293407	WELL	PR	02/13/2012	GW	045-14967	SCHOOL HOUSE POINT OM 05C L15 696	PR
293408	WELL	PR	01/13/2012	GW	045-14968	SCHOOL HOUSE POINT OM 12B L15 696	PR
293409	WELL	PR	01/13/2012	GW	045-14969	SCHOOL HOUSE POINT OM 13D L15 696	PR
293410	WELL	PR	08/19/2011	GW	045-14970	SCHOOL HOUSE POINT OM 12D L15 696	PR

**General Comment:**

ECMC Inspection Report Summary

On Friday 11/15/2024, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus Granlee OM L15, at Location # 335979 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Access roads shows signs of lack of stabilization/ compaction and no evidence of tracking controls.
  2. 95 BBL condensate tank is open to atmosphere.
  3. Random debris.
  4. Manway on tank is open for wildlife to enter.
- Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911/970-285-2615

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Manway on tank is open for wildlife to enter.		
Corrective Action:	Eliminate possibility of wildlife to enter openings	Date:	12/06/2024
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	12/06/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 3		corrective date
Comment:	2 chemical tanks in plastic containments and 1 500 methanol tank in metal cuntainment		
Corrective Action:		Date:	

Type: Bradenhead	# 7	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 7	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 7	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 9	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:	No meter on flow line	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLs	STEEL AST		,
Comment:	95 BBL condensate tank is open to atmosphere.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal					
Comment:	Buried half way				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	293404	Type:	WELL	API Number:	045-14964	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	293405	Type:	WELL	API Number:	045-14965	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	293406	Type:	WELL	API Number:	045-14966	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	293407	Type:	WELL	API Number:	045-14967	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	293408	Type:	WELL	API Number:	045-14968	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	293409	Type:	WELL	API Number:	045-14969	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	293410	Type:	WELL	API Number:	045-14970	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse to none
		Culverts				
		Sediment Traps				
		Ditches				
		Compaction				Light compaction in areas

Comment: Places with sparse to no gravel & light compaction are present on lease road. At the time of this inspection the location and portions of access road are snow covered; maintenance may be necessary to prevent degradation to the lease roads in the near future. Sparse to no gravel and light compaction could lead to future stabilization issues.

Corrective Action: Maintenance relative to storm water runoff, operators shall consider seasonal factors, such as winter snow cover and spring runoff from snowmelt, to ensure site conditions and controls are adequate and in place to effectively manage storm water.

Date: \_\_\_\_\_

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404006849	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6800627">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6800627</a>
707801247	Photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6800605">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6800605</a>