

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/25/2024

Submitted Date:

11/25/2024

Document Number:

708905097**FIELD INSPECTION FORM**Loc ID 334886 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**34 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
QB Energy		ecmc.inspections@qb-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211534	WELL	PR	06/01/2002	GW	045-07294	SHIDELER 19-8	PR
261628	WELL	PR	04/29/2003	GW	045-07968	SHIDELER 19-9B1 (H19)	PR
261629	WELL	PR	05/01/2003	GW	045-07969	SHIDELER 19-7DI (H19)	PR
264086	WELL	PR	04/14/2003	GW	045-08174	HMU 19-2D1 (H19)	PR
264087	WELL	PR	09/01/2018	GW	045-08175	HMU 19-3DI (H19)	PR
264088	WELL	PR	05/01/2003	GW	045-08176	HMU 19-1B1 (H19)	PR

**General Comment:****CECMC Inspection Report Summary**

On 11/25/2024 at approximately 13:06 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at QB Energy SHIDELER 19-8 (H19) Pad.

Location # 334886 in Garfield County Colorado.

Please refer to inspection 708903003 conducted on 02/07/2024, previous corrective actions have been completed.

Location is within High Priority/Density/Black Bear Habitat areas.

Drainage contributes to Middle Mamm Creek.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Flowline heating insulation open ended/wildlife hazard with a CA date of 12/02/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Sign at start of lease road		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellhead signs at separators		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Small amount of staining near some wellheads		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Summit Midstream meter house - bollards		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Pig station - pipe rail fence		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tank - cattle panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 6		corrective date
Comment:	Pressure transducers located on all bradenheads, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	1 Flowline heating insulation open ended/wildlife hazard/available for entry by wildlife 1 Flowline heating insulation damaged/wildlife hazard/available for entry by wildlife		
Corrective Action:	Comply with CECMC wildlife rules	Date:	12/02/2024
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		

Comment:	19-8 well not on plunger lift			
	Remaining 5 wells on plunger lift			
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:	Summit Midstream			
Corrective Action:			Date:	
Type: Gas Meter Run	# 6			
Comment:				
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
Comment:	Centralized containment				
	Unlined containment				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST		,	
Comment:	Tanks equipped with telemetry					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment:	Centralized containment				
	Unlined containment				
Corrective Action:					Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities				
Facility ID:	211534	Type:	WELL	API Number: 045-07294 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	261628	Type:	WELL	API Number: 045-07968 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	261629	Type:	WELL	API Number: 045-07969 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	264086	Type:	WELL	API Number: 045-08174 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	264087	Type:	WELL	API Number: 045-08175 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	264088	Type:	WELL	API Number: 045-08176 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps						
		Ditches				
Compaction						Light compaction in some areas
Berms						
		Gravel				Sparse to none
		Compaction				Light compaction in some sections
Gravel						Sparse to none in areas
				Material Handling And Spill Prevention		Chemical tank containment
		Culverts				
Rip Rap						
Tracking Pad						Aggregate/gravel based VTC at entrance to location

Comment: 

Some fluid in chemical tank containment, may need maintenance in the near future.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Equipment for corrective action & also refer to Stormwater for comments.	smelserw	11/25/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404007113	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6801074">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6801074</a>
708905098	Inspection 708905097 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6801072">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6801072</a>
708905099	Inspection 708905097 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6801073">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6801073</a>