

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/21/2024

Submitted Date:

11/25/2024

Document Number:

709100454

FIELD INSPECTION FORM

Loc ID: 458288
Inspector Name: Heibel, Krystal
On-Site Inspection:
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10032
Name of Operator: H & M PETROLEUM CORPORATION
Address: 9708 WAYNE RD
City: CHEYENNE State: WY Zip: 82009

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Cindy Buysee		tcbuysee@hotmail.com	
Tom Buysee	320-761-8865	tom@tomsfoodpride.net	
Matthew Mondero	785-475-4299	matt@greatplainsenergyinc.com	
Dick Shanor		dick.shanor@gmail.com	
Krystal Heibel		krystal.heibel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
458288	LOCATION	AC			-	State BDB 1 Pad	EI
458364	WELL	PR	01/01/2023	OW	075-09430	State BDB 1	EG

General Comment:

This is an environmental progress inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site conditions.

Previous Field Inspection Reports:

Doc# 709100133; Inspection Date: October 18, 2023; Inspector: Krystal Heibel
Doc# 708200603; Inspection Date: October 5, 2023; Inspector: Dylan Edwardson

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Signage present		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Good Housekeeping:

Type			
Comment:	Unused equipment stored on site: piping and wire. / Comply with Rule 606. / CA Date: 11/13/2023		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			
Comment:	Hydrocarbon impacted soils located throughout the site: near the wellhead, within the meter shed, under various open piping throughout site, and next to the pumping unit.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Operator shall submit a Form 19 (Spill/Release Report) to webforms to document the remediation of this spill/release. Operator shall collect confirmation soil samples as described in the Rule 915.e.(2) Guidance Document. Operator will analyze soil samples for TPH (C6-C36), Table 915-1 Organic Compounds in Soil, Table 915-1 metals, and Table 915-1 Soil Suitability for Reclamation (Electrical conductivity, Sodium adsorption ratio, and pH by saturated paste method, boron (hot water soluble)).				Date: 11/28/2023

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

					corrective date
Type:	#				
Comment:	Valves not bull plugged or secured; See photo documentation for more information; Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.				
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:					Date:	

Paint

Condition	<input style="width: 95%;" type="text"/>		
Other (Content)	<input style="width: 95%;" type="text"/>		

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Burrows present and observed; See Photo Documentation; Repair or install berms or other secondary containment devices per Rule 603.o.			
Corrective Action:				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 458288 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458364 Type: WELL API Number: 075-09430 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404006315	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6800149
709100455	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6800134