

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 89-17 Pad

Location #: 335063



Photo # 1270 From entrance to location




Photo # 1271 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 89-17 Pad

Location #: 335063

Nov 26, 2024 at 10:12:56 AM  
CO



Photo # 1272 Location

Nov 26, 2024 at 10:14:04 AM



Photo # 1273 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 89-17 Pad

Location #: 335063



Photo # 1274 Location

Photo # 1275 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 89-17 Pad

Location #: 335063



Photo # 1276 Location



Photo # 1277 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 89-17 Pad

Location #: 335063



Photo # 1278 Location



Photo # 1279 Liquid nitrogen tank does not appear to be listed on Form 2A or Form 4 SUNDRY/not in compliance with CECMC rules

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 89-17 Pad

Location #: 335063



**Photo # 1280 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 1281 PRV vent line does not comply with CECMC pressure safety device rules**


## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 89-17 Pad

Location #: 335063



**Photo # 1282 PRV vent lines do not comply with CECMC pressure safety device rules**



**Photo # 1283 PRV vent lines do not comply with CECMC pressure safety device rules**