

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/12/2024

Submitted Date:

12/02/2024

Document Number:

718100015**FIELD INSPECTION FORM**Loc ID 442549 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1700 LINCOLN ST STE 3950City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Katz, Aaron		aaron.katz@state.co.us	
, Laramie		cogccnotifications@laramie-energy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442549	LOCATION	AC			-	Piceance 28-10 Pad	RI
442560	WELL	PR	07/29/2016	GW	077-10256	Piceance Fed 28-20E	RI
442564	WELL	PR	07/25/2016	GW	077-10259	Piceance Fed 28-17E	RI

**General Comment:**

On 11/12/2024, Western Reclamation Work Lead Trujillo conducted an inspection at Laramie Energy LLC's Piceance/28-10 Pad Location in Mesa County, Colorado.

This inspection is a follow-up to #696206345 to document compliance with the following corrective actions:

- Spill Cleanup
- Caps/Plugs at tanks

This inspection is also in response to FIRR #403949488 stating CAs have been completed; it was observed in this inspection that the CAs have been resolved.

The following compliance issues were observed during this inspection:

- Spill/leak at wells
- Stormwater

Due to technical difficulties, inspector was unable to submit this inspection report within an appropriate timeframe- Operator was provided notice of the compliance issues and corrective action requirements in an email on 12/15/2024.

Refer to the Location and Stormwater sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-800-897-6191 / 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Pipe equipment previously observed stored next to wells have been removed.		
Corrective Action:		Date:	
Type	WEEDS		
Comment:	Refer to Inspection #696206345 regarding weeds.		
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	
Other	WELLHEAD		
Comment:	A leak was detected at the Piceance Fed 28-17E, and the Piceance Fed 28-20E wells. Operator on Location was provided notice of the leak and Operator was provided notice of the CA requirment verbally and via email.		
Corrective Action:	Stop leaks at the wells- Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 11/19/2024

In Containment: No

Comment: Spill cleanup requirements per inspection #696206345 have been resolved.

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type:	#		
Comment:	603.i requirement per inspection #696206345 has been resolved.		
Corrective Action:		Date:	

**Venting:**

Yes/No		
--------	--	--

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	442549	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	442560	Type:	WELL	API Number:	077-10256	Status:	PR	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	442564	Type:	WELL	API Number:	077-10259	Status:	PR	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		BMPs to stabilize the working pad surface, as well as to minimize tracking and sediment transport are in disrepair; the working pad surface lacks stabilization and tracking is evident.				
Corrective Action:		Comply with Rule 1002.f				Date: 11/22/2024
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718100016	Leak at the Fed 28-20E Well	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6807441">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6807441</a>
718100017	Leak at the Fed 28-17E Well	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6807442">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6807442</a>
718100018	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6807443">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6807443</a>