

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/25/2024

Submitted Date:

11/25/2024

Document Number:

713301343**FIELD INSPECTION FORM**Loc ID 318123 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|--------------|---------------------------|---------------------------------|
| Silver, Randy | 720-827-6688 | randy.silver@state.co.us | |
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| , KPK | 303-825-4822 | cogcc@kpk.com | all inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 240647 | WELL | SI | 05/01/2021 | OW | 123-08435 | COSSLETT A 4 | SI |

General Comment:[follow up inspection](#)

LocationOverall Good: ☐

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | good | | |
| Corrective Action: | | Date: | |

| | |
|---------------------------|-------------|
| Emergency Contact Number: | |
| Comment: | |
| Corrective Action: | Date: _____ |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|-----------------------------------|-------|--|
| Fencing/: | | | |
| Type | OTHER | | |
| Comment: | electric disconnect, metal panels | | |
| Corrective Action: | | Date: | |
| Type | PUMP JACK | | |
| Comment: | safety guards | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|----------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 3 | | |
| Comment: | electric/automation panels | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | pipd to surface | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | electric | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 240647 Type: WELL API Number: 123-08435 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTED

Comment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Valves appeared to be closed at time of inspection

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 04/29/2024**BradenHead**Date of Last Brhd Test: 05/06/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|---|---------|------------|
| <u>ECMC Inspection Report Summary</u> <u>Inspector Michael Kester,</u> <u>conducted an on-site Follow up inspection as per doc# 713300751 in accordance with Rule 901a,</u> <u>corrective actions appeared to have NOT been addressed</u> <u>Location: Cosslett A4</u> <u>Operator: KPK</u> <u>API#: 123-08435</u> <u>County: Weld</u> <u>Mechanical integrity Testing, Rule 417b, corrective action date 4-29-2024</u> <u>Weather conditions: clear and dry</u> <u>This inspection does not nullify any orders or NOAV from the ECMC</u> | kesterm | 11/25/2024 |

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404007226 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6801308 |
| 713301344 | site pic | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6801292 |