

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/27/2024

Submitted Date:

11/27/2024

Document Number:

708905113

FIELD INSPECTION FORM

 Loc ID 335136 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num:

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 16 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:

 ECMC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635

Contact Information:

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211215	WELL	PR	12/19/1995	GW	045-06974	FEDERAL RMV-33-20	PR
265048	WELL	PR	01/07/2004	OW	045-08978	FEDERAL RWF 334-17	PR
265049	WELL	PR	09/23/2002	OW	045-08979	FEDERAL RWF 344-17	PR
279142	WELL	PR	08/03/2005	GW	045-11004	GARFIELD COUNTY RWF 541-20	PR
279146	WELL	PR	08/03/2005	GW	045-11008	GARFIELD COUNTY RWF 441-20	PR

General Comment:

CECMC Inspection Report Summary

On 11/27/2024 at approximately 13:24 hours, I, Compliance Specialist, Wayne Smelser
 Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC FEDERAL RMV 33-20 pad.
 Location # 335136 in Garfield County Colorado.

Please refer to inspection 708905103 conducted on 11/26/2024, previous corrective action has not been completed.

Location is within High Priority/Density Habitat areas.

Location is inside the Garfield County Landfill.

During this inspection the following compliance issues were observed:

1. Equipment - Mechanical Condition - possible bradenhead leak on the RMV 33-20 well with a CA date of 11/27/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Remote location/split pad - Wellheads only, production equipment for these 5 wells is located on the CLOUGH 135, location # 322438

Location			
Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
Equipment:			
Type: Deadman # & Marked	# 3		corrective date
Comment:	Marked		
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Mechanical Condition - possible bradenhead leak on the RMV 33-20 well		
	Please refer to inspection 708905103 conducted on 11/26/2024, previous corrective action has not been completed & CA date remains 11/27/2024		
Corrective Action:	All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition.		Date: 11/27/2024
Type: Bradenhead	# 5		

<p>Comment:</p>	<p>RMV 33-20 & RWF 334-17 wells have Taylor plugs on bradenheads, bradenhead valves are accessible.</p> <p>Remaining 3 wells have no form of pressure monitoring equipment located on bradenheads, bradenhead valves are accessible.</p> <p>FEDERAL RMV 33-20 Well's bradenhead pressure is 38.9% of the TVD in feet of the surface casing shoe expressed in psig. FORM 4 SUNDRY document # 402766833 submitted on 08/06/2021 operator requested increased threshold pressure.</p>		
<p>Corrective Action:</p>		<p>Date:</p>	

Venting:

<p>Yes/No</p>	<p>NO</p>		
<p>Comment:</p>			
<p>Corrective Action:</p>		<p>Date:</p>	

Flaring:

<p>Type</p>			
<p>Comment:</p>			
<p>Corrective Action:</p>		<p>Date:</p>	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Limited Stormwater inspection due to snow.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Equipment for corrective action	smelserw	11/27/2024
Remote location/Split pad - Wellheads only, production equipment for these 5 wells located on the CLOUGH 135, location # 322438		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404010639	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6804756
708905114	Inspection 708905113 FEDERAL RMV 33-20 bradenhead leak video 1	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6804753
708905115	Inspection 708905113 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6804754
708905116	Inspection 708905113 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6804755