

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

11/16/2023

Document Number:

403573369

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

OGCC Operator Number: 10633 Contact Person: James Miller
Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (720) 984-7460
Address: 555 17TH STREET SUITE 3700 Email: jmiller@civiresources.com
City: DENVER State: CO Zip: 80202

Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes No

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 336366 Location Type: Production Facilities
Name: SALISBURY Number: 14-11
County: WELD
Qtr Qtr: SWSW Section: 11 Township: 2N Range: 68W Meridian: 6
Latitude: 40.149395 Longitude: -104.976291

Description of Corrosion Protection

Crestone pipelines are covered in a protective external coating. Flowlines are subject to thorough inspections and fabrication standards during installation to minimize coating and pipe defects. Crestone maintains a chemical program to reduce internal corrosion. If a flowline is found to lack integrity, Crestone will investigate, report, and remediate any spills in accordance with the 900 series rules.

Description of Integrity Management Program

Crestone flowlines are pressure tested prior to placing flowlines into service. Flowlines are tested on an annual basis in accordance with COGCC 1104 series rules. If a flowline is found to lack integrity, Crestone will investigate the root cause, as well as report and remediate any spills in accordance with the 900 series rules. All repairs will be completed in accordance with COGCC 1102 Series rules.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 473314 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 336366 Location Type: Well Site
Name: SALISBURY Number: 14-11
County: WELD No Location ID
Qtr Qtr: SWSW Section: 11 Township: 2N Range: 68W Meridian: 6
Latitude: 40.149395 Longitude: -104.976291

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: Native Materials Date Construction Completed: 10/05/2007
Maximum Anticipated Operating Pressure (PSI): 650 Testing PSI:
Test Date:

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 10/22/2022

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

The flowline servicing the Salisbury 13-11 (05-123-26243) is now out of service as per rule 1102.O.(2). The most recent successful pressure test was conducted 6/17/2017.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 473316 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 336366 Location Type: Well Site
Name: SALISBURY Number: 14-11
County: WELD No Location ID
Qtr Qtr: SWSW Section: 11 Township: 2N Range: 68W Meridian: 6
Latitude: 40.149395 Longitude: -104.976291

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: Native Materials Date Construction Completed: 10/26/1976
Maximum Anticipated Operating Pressure (PSI): 650 Testing PSI:
Test Date:

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 10/22/2022

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

The flowline servicing the SALISBURY 1 (05-123-08614) is now out of service as per rule 1102.O.(2). The most recent successful pressure test was conducted 6/17/2017.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 473317 Flowline Type: Wellhead Line Action Type: _____

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 336366 Location Type: Well Site
Name: SALISBURY Number: 14-11
County: WELD No Location ID
Qtr Qtr: SWSW Section: 11 Township: 2N Range: 68W Meridian: 6
Latitude: 40.149395 Longitude: -104.976291

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: Native Materials Date Construction Completed: 10/06/2011
Maximum Anticipated Operating Pressure (PSI): 650 Testing PSI: _____
Test Date: _____

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 10/22/2022

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

The flowline servicing the Salisbury 2-4-11 (05-123-31924) is now out of service as per rule 1102.O.(2). The most recent successful pressure test was conducted 6/17/2017.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 473315 Flowline Type: Wellhead Line Action Type: Realignment

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 336366 Location Type: Well Site
Name: SALISBURY Number: 14-11
County: WELD No Location ID
Qtr Qtr: SWSW Section: 11 Township: 2N Range: 68W Meridian: 6

Latitude: 40.149395 Longitude: -104.976291

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000

Bedding Material: Native Materials Date Construction Completed: 11/30/2011

Maximum Anticipated Operating Pressure (PSI): 650 Testing PSI: _____

Test Date: _____

OFF LOCATION FLOWLINE Realignment

Date: 10/20/2023

Description of Realignment:

The flowline servicing the Salisbury 14-11 (05-123-31926) has been out of service as per rule 1102.O. Prior to switching to active status a form 42 was submitted prior to a pressure test on doc #403563678. A form 42 prior to returning to service was reported on doc #403563699. Flowline is returned to normal operations and testing requirements.

OPERATOR COMMENTS AND SUBMITTAL

Comments Form 44 filed to report STATUS CHANGE notification. The following flowline(s) are now active:
12331926_FL: services the Salisbury 14-11 (05-123-31926)
All other flowlines will remain as previously reported.
Updated GIS data attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: _____ Date: 11/16/2023 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Director of COGCC Date: _____

Conditions of Approval

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

403597525	OFF-LOCATION FLOWLINE GIS SHP
-----------	-------------------------------

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval

Total: 0 comment(s)