

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2024

Submitted Date:

12/04/2024

Document Number:

697010490

FIELD INSPECTION FORMLoc ID 332832 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295716	WELL	PR	01/01/2020	OW	123-25792	FR-LORENZ 11-17-11	SI
420925	WELL	SI	01/01/2024	GW	123-32751	Front Range 11-17-5	SI
420928	WELL	SI	06/01/2024	GW	123-32754	Front Range 11-17-6	SI
420929	WELL	PR	05/01/2017	OW	123-32755	Front Range 11-17-8	SI
420936	WELL	PR	05/01/2017	OW	123-32762	Front Range 11-17-7	SI
420937	WELL	SI	09/01/2024	OW	123-32763	Front Range 11-17-10	SI

General Comment:

This is a routine audit. Any corrective actions from previous audits that have not been addressed are still applicable. There were operator personnel on location at the time of this field audit.

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	x 6		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe fencing x 5		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	#		
Comment:	Automation array, ECD scrubbers		
Corrective Action:		Date:	
Type: Flow Line	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment:	Bradenhead valves are exposed at surface.		
Corrective Action:		Date:	
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 4		

Inspector Name: Peterson, Tom

Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	DCP calibration card is current.		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:	Lined berm				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	OTHER	STEEL AST		,
Comment:	286 bbls				
Corrective Action:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: Lined berm					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: Lined berm					
Corrective Action:					Date:
<u>Venting:</u>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<u>Flaring:</u>					
Type					
Comment:					
Corrective Action:					Date:

Inspected FacilitiesFacility ID: 295716 Type: WELL API Number: 123-25792 Status: PR Insp. Status: SI**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 08/30/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 420925 Type: WELL API Number: 123-32751 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 10/31/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 420928 Type: WELL API Number: 123-32754 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 01/19/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 420929 Type: WELL API Number: 123-32755 Status: PR Insp. Status: SI

Producing Well			
Comment:			
Corrective Action:			Date:

BradenHead			
Date of Last Brhd Test:	03/22/2024	Annual Brhd Completed?	Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 0	Fluid Type:	
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:			Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	420936	Type:	WELL	API Number:	123-32762	Status:	PR	Insp. Status:	SI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:			
Corrective Action:			Date:

BradenHead			
Date of Last Brhd Test:	02/02/2024	Annual Brhd Completed?	Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 0	Fluid Type:	
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:			Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	420937	Type:	WELL	API Number:	123-32763	Status:	SI	Insp. Status:	SI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Idle Well			
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder:
Comment:			
Corrective Action:			Date:

BradenHead			
Date of Last Brhd Test:	09/26/2024	Annual Brhd Completed?	Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 0	Fluid Type:	
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:			Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

--	--	--	--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697010491	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6811393