

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/02/2024

Submitted Date:

12/04/2024

Document Number:

713400508**FIELD INSPECTION FORM**

| | | | | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------|---------------------------------------------|-------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Loc ID 418985 | Inspector Name: Popejoy, Dusty | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 42 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested |
| Operator Information: ECMC Operator Number: <u>10433</u> Name of Operator: <u>LARAMIE ENERGY LLC</u> Address: <u>1700 LINCOLN ST STE 3950</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80203</u> | | | | ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE |

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|-------|---------------------------------------|---------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| , LARAMIE | | cogccnotifications@laramie-energy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 419015 | WELL | PR | 04/01/2018 | GW | 077-10101 | Bruton 30-16B | PR |
| 419019 | WELL | PR | 07/09/2013 | GW | 077-10102 | Bruton 30-10B | PR |
| 419027 | WELL | PR | 04/01/2018 | GW | 077-10103 | Bruton 30-08B | PR |
| 419043 | WELL | PR | 04/01/2018 | GW | 077-10104 | Bruton 30-06B | PR |
| 452121 | WELL | PR | 12/09/2018 | GW | 077-10466 | Bruton 30-21E | PR |
| 452122 | WELL | PR | 12/09/2018 | GW | 077-10467 | Bruton 30-20E | PR |
| 452123 | WELL | PR | 11/06/2018 | GW | 077-10468 | Bruton Federal 30-17W | PR |
| 452124 | WELL | PR | 12/11/2018 | GW | 077-10469 | Bruton Federal 30-19W | PR |
| 452125 | WELL | PR | 11/06/2018 | GW | 077-10470 | Bruton 30-15E | PR |
| 452126 | WELL | PR | 11/09/2018 | GW | 077-10471 | Bruton 30-14E | PR |
| 452127 | WELL | PR | 11/07/2018 | GW | 077-10472 | Bruton 30-16W | PR |
| 452128 | WELL | PR | 12/14/2018 | GW | 077-10473 | Bruton 30-19E | PR |
| 452129 | WELL | PR | 12/16/2018 | GW | 077-10474 | Bruton Federal 30-20W | PR |
| 452130 | WELL | PR | 12/07/2018 | GW | 077-10475 | Bruton Federal 31-01E | PR |
| 452131 | WELL | PR | 12/16/2018 | GW | 077-10476 | Bruton Federal 30-21W | PR |
| 452132 | WELL | PR | 11/07/2018 | GW | 077-10477 | Bruton 30-17E | PR |
| 452133 | WELL | PR | 11/05/2018 | GW | 077-10478 | Bruton 30-14W | PR |
| 452134 | WELL | PR | 11/08/2018 | GW | 077-10479 | Bruton 30-16E | PR |
| 452135 | WELL | PR | 11/03/2018 | GW | 077-10480 | Bruton 30-15W | PR |
| 452138 | WELL | PR | 12/12/2018 | GW | 077-10481 | Bruton Federal 30-18W | PR |

General Comment:

CECMC Inspection Report Summary

On 12/2/2024 at approximately 14:29 hours, Compliance Inspector Dusty Popejoy conducted a follow up inspection at LARAMIE ENERGY LLC Bruton/30-10 Pad at Location ID #418985 in Mesa County, Colorado.

Please refer to inspection 713400325 conducted on 09/17/2024, 1 of 3 corrective actions have been completed. Loose barbed wire/wildlife hazard & Open ended load line have not been completed & CA dates remain the same.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1. Housekeeping - Loose barbed wire/wildlife hazard with a CA date of 9/26/2024
2. Equipment - Open ended load line with a CA date of 9/29/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location**Lease Road:**

| | | | |
|-------------------|--------|-------|--|
| Type | Access | | |
| comment: | Access | | |
| Corrective Action | L | Date: | |

Overall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|--|
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | Chemical tanks | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Sign at entrance to location | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|--------------------|-------------|
| Comment: | 1-800-891-6191/911 | |
| Corrective Action: | | Date: _____ |

Good Housekeeping:

| | | | |
|--------------------|------------------------------------------------------------|-------|------------|
| Type | OTHER | | |
| Comment: | Loose barbed wire fencing/wildlife hazard, refer to photos | | |
| Corrective Action: | Comply with CECMC wildlife rules | Date: | 09/26/2024 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | | |
|---------------------------------|--------------------------------------------------------------------|----------|-------|-----------------|
| Fencing/: | | | | |
| Type | OTHER | | | |
| Comment: | Chemical tanks - Hog panels | | | |
| Corrective Action: | | | Date: | |
| Type | WELLHEAD | | | |
| Comment: | Hog panels/Barbed wire | | | |
| Corrective Action: | | | Date: | |
| Equipment: | | | | corrective date |
| Type: Bradenhead | # 20 | | | |
| Comment: | All Bradenhead valves are accessible with telemetry for monitoring | | | |
| Corrective Action: | | | Date: | |
| Type: Emission Control Device | # 1 | | | |
| Comment: | ECD equipped with knockout tank | | | |
| Corrective Action: | | | Date: | |
| Type: Plunger Lift | # 20 | | | |
| Comment: | All wells on plunger lift | | | |
| Corrective Action: | | | Date: | |
| Type: Ancillary equipment | # 2 | | | |
| Comment: | Chemical tanks | | | |
| Corrective Action: | | | Date: | |
| Type: Other | # 1 | | | |
| Comment: | Open ended load line, refer to photos | | | |
| Corrective Action: | All load lines will be capped or plugged | | Date: | 09/29/2024 |
| Type: Ancillary equipment | # 1 | | | |
| Comment: | Thermoelectric generator | | | |
| Corrective Action: | | | Date: | |
| Type: Bird Protectors | # 6 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type: Vertical Heated Separator | # 20 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type: Gas Meter Run | # 20 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type: Pig Station | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Tanks and Berms: | | | | |
| Contents | # | Capacity | Type | Tank ID |
| | | | | SE GPS |

| | | | | | | |
|----------------------------------------|----------|---------------------|---------------------|-------------|--------|-------|
| CONDENSATE | 1 | 400 BBLs | HEATED STEEL AST | | | |
| Comment: Tank equipped with telemetry | | | | | | |
| Corrective Action: | | | | | | Date: |
| <u>Paint</u> | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| <u>Berms</u> | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Metal | Adequate | Walls Sufficient | | | | |
| Comment: Centralized containment | | | | | | |
| Corrective Action: | | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CONDENSATE | 7 | 400 BBLs | STEEL AST | | | |
| Comment: Tanks equipped with telemetry | | | | | | |
| Corrective Action: | | | | | | Date: |
| <u>Paint</u> | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| <u>Berms</u> | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Metal | Adequate | Walls Sufficient | | | | |
| Comment: Centralized containment | | | | | | |
| Corrective Action: | | | | | | Date: |
| <u>Venting:</u> | | | | | | |
| Yes/No | NO | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| <u>Flaring:</u> | | | | | | |
| Type | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

| Inspected Facilities | | | | | | | | | |
|------------------------------------------------------------------------------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 419015 | Type: | WELL | API Number: | 077-10101 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 419019 | Type: | WELL | API Number: | 077-10102 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 419027 | Type: | WELL | API Number: | 077-10103 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 419043 | Type: | WELL | API Number: | 077-10104 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 452121 | Type: | WELL | API Number: | 077-10466 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 452122 | Type: | WELL | API Number: | 077-10467 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 452123 | Type: | WELL | API Number: | 077-10468 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 452124 | Type: | WELL | API Number: | 077-10469 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |

| <u>Producing Well</u> | | | | |
|------------------------------------------------------------------------------------------|----------------|-------|-------|---------------------------------------------------|
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | |
| Facility ID: | 452125 | Type: | WELL | API Number: 077-10470 Status: PR Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | |
| Facility ID: | 452126 | Type: | WELL | API Number: 077-10471 Status: PR Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | |
| Facility ID: | 452127 | Type: | WELL | API Number: 077-10472 Status: PR Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | |
| Facility ID: | 452128 | Type: | WELL | API Number: 077-10473 Status: PR Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | |
| Facility ID: | 452129 | Type: | WELL | API Number: 077-10474 Status: PR Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | |
| Facility ID: | 452130 | Type: | WELL | API Number: 077-10475 Status: PR Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | |
| Facility ID: | 452131 | Type: | WELL | API Number: 077-10476 Status: PR Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: | Producing well | | | |

| | | | | | | | | | |
|------------------------------------------------------------------------------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Corrective Action: | | Date: | | | | | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 452132 | Type: | WELL | API Number: | 077-10477 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 452133 | Type: | WELL | API Number: | 077-10478 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 452134 | Type: | WELL | API Number: | 077-10479 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 452135 | Type: | WELL | API Number: | 077-10480 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 452138 | Type: | WELL | API Number: | 077-10481 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|----------------------------------------|--------------------------|----------------------------|
| | | Ditches | | | | |
| Compaction | | | | | | |
| | | | | Material Handling And Spill Prevention | | Chemical tank containments |
| Berms | | | | | | |
| Ditches | | | | | | |
| | | Berms | | | | |
| Culverts | | | | | | |
| | | Compaction | | | | |

Comment: Limited storm water inspection due to snow cover

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|------------------------------------------------------------------|----------|------------|
| Please refer to Housekeeping & Equipment for corrective actions. | popejoyd | 12/04/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 713400509 | Inspection Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6811794 |