

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/02/2024

Submitted Date:

12/05/2024

Document Number:

708700070

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Kosola, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Findings:**

2 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
, SIMCOE		sjninspections@ikavenergy.co	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488582	SPILL OR RELEASE	AC	12/03/2024		-	Clovis A2 Line Release	EI

**General Comment:**

This is an environmental inspection to document status of a reported spill of coal bed methane produced water. Operator reported spill may have impacted irrigation ditch adjacent to well pad. See attached photos and corrective action on the Environmental tab.  
No flowing water was observed in the irrigation ditch at the time of inspection.

**Inspected Facilities**

Facility ID: 488582 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spills/Releases:**

Type of Spill: PRODUCED WATER Estimated Spill Volume: \_\_\_\_\_

Comment: Operator reported a spill of produced water of unknown volume. Spill appears to have flowed north from well pad, west through culvert under lease road, and into irrigation ditch located on the west side of the well pad.

Corrective Action: Operator shall delineate the full horizontal and vertical extent of spill and remove and/or remediate impacts within 90 days of discovery of spill. If clean up of spill will exceed 90 days Operator shall submit a Form 27 Initial Remediation Plan to Area EPS.

Date: 02/28/2025

Reportable: YES GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708700071	Inspection photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6812173">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6812173</a>