

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/05/2024

Submitted Date:

12/05/2024

Document Number:

716201364**FIELD INSPECTION FORM**Loc ID 332902 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Oxy		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263471	WELL	SI	09/01/2024	GW	123-20891	SARCHET 8-23A	PA

General Comment:

This is a routine Plug & Abandonment audit.

Well has been plugged with night cap and fencing surrounding wellhead.

Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Corrective Action: Date: **Equipment:**

corrective date

Type: Plunger Lift

0

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment: Battery location number: 436532					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

PaintCondition Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: <input type="text"/>				
Corrective Action: <input type="text"/>				Date: <input type="text"/>

Venting:Yes/No Comment: Corrective Action: Date: **Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 263471 Type: WELL API Number: 123-20891 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716201365	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6812492