

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/05/2024

Submitted Date:

12/05/2024

Document Number:

713301369

FIELD INSPECTION FORM

Loc ID 458074 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10583
Name of Operator: PETRO OPERATING COMPANY LLC
Address: 9033 E EASTER PLACE SUITE 112
City: CENTENNIAL State: CO Zip: 80112-

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|-------|-----------------------|---------|
| Parker, Roger | | rogeraparker9@aol.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 458075 | WELL | PR | 12/21/2021 | OW | 001-10204 | BEF WEST 11 | PR |
| 458076 | WELL | EP | 10/16/2020 | LO | 001-10205 | BEF WEST 13 | EP |
| 458083 | WELL | EP | 10/16/2020 | LO | 001-10212 | BEF WEST 4 | EP |
| 458085 | WELL | AL | 07/19/2023 | LO | 001-10214 | BEF WEST 12 | AL |
| 458087 | WELL | PA | 12/29/2021 | OW | 001-10215 | BEF WEST 14 | PA |
| 458091 | WELL | PA | 12/29/2021 | OW | 001-10219 | BEF WEST 15 | PA |
| 458144 | WELL | PA | 12/29/2021 | OW | 001-10222 | BEF WEST 16 | PA |

General Comment:

well site inspection

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 458075 Type: WELL API Number: 001-10204 Status: PR Insp. Status: PR

Producing Well

Comment: PR, valves appeared to be open at time of inspection

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 09/01/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458076 Type: WELL API Number: 001-10205 Status: EP Insp. Status: EP

Idle Well

Purpose: Shut In Temporarily Abandoned

Reminder: _____

Comment: Well has expired permit, waiting on operator to submit Abandoned Location status

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458083 Type: WELL API Number: 001-10212 Status: EP Insp. Status: EP

Idle Well

Purpose: Shut In Temporarily Abandoned

Reminder: _____

Comment: Well has expired permit, waiting on operator to submit Abandoned Location status

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458085 Type: WELL API Number: 001-10214 Status: AL Insp. Status: AL

Idle Well

Purpose: Shut In Temporarily Abandoned

Reminder: _____

Comment: Suspended operations, well not drilled

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458087 Type: WELL API Number: 001-10215 Status: PA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned

Reminder: _____

Comment: P&A 12-29-2021

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458091 Type: WELL API Number: 001-10219 Status: PA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458144 Type: WELL API Number: 001-10222 Status: PA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|---|---------|------------|
| Audit of scout card and related documents Routine inspection | kesterm | 12/05/2024 |
| This inspection does not nullify any orders or NOAV from the ECMC | | |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 713301370 | site pic | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6812829 |