

## Ashley Logan

---

**From:** Steve Wheeler, P.E. <steven.wheeler@state.co.us>  
**Sent:** Friday, December 22, 2023 7:45 AM  
**To:** Ashley Logan  
**Cc:** Ellice Devine - DNR; Regulatory; DL Flowlines; Branden Ferguson  
**Subject:** Re: Flowline Abandonment Field Change

Ash,

That asbestos is tough to deal with and it's been found recently among other operators too. Thanks for the updates, we'll look for the removals at facility closures.

-Steve

On Thu, Dec 21, 2023 at 10:51 AM Ashley Logan <[alogan@civiresources.com](mailto:alogan@civiresources.com)> wrote:

Good morning Steve,

I left a message earlier about some field changes to flowline abandonment type. These flowlines were originally submitted for removal, but due to time constraints/safety reasons the abandonment type was changed to abandonment in place. There have been on-going conversations with surface owner about schedule changes and wildlife restrictions. See details below:

- Aristocrat 21-10 (05-123-09497) Pre-AB Doc # 403470374
  - Abandonment type changed to ABiP due to being found to be asbestos coated. This flowline is in an eagle buffer zone and there was not enough time to fully expose and abate before the end of the season. Plan to remove in 8/2024 when Eagle HPH allows.
- Marick 15-29 (05-123-26330) Pre-AB Doc # 403508003
  - Abandonment type changed to ABiP for safety reasons. On initial inspection it looked like the line could be removed, but once the field got into the work, they determined it could not be removed safely due to its proximity to a sales line so it was ABiP instead. When the facility is decommissioned the flowline will be fully removed.
- Aristocrat 24-03C (05-123-12821) Pre-AB Doc # 403310038
  - Abandonment type changed to ABiP due to being found to be asbestos coated. This flowline is in an eagle buffer zone and there was not enough time to fully expose and abate before the end of the season. Plan to remove in 8/2024 when Eagle HPH allows.
- Aristocrat Angus 7-2-10 (05-123-23015) Pre-AB Doc # 403470340
  - Abandonment type changed to partial ABiP due to being found to be asbestos coated. This flowline is in an eagle buffer zone and there was not enough time to fully expose and abate before the end of the season. Plan to remove in 8/2024 when Eagle HPH allows.

Thank you,

**Ash Logan**

Civitas Resources, Inc.

[alogan@civiresources.com](mailto:alogan@civiresources.com)

Mobile: 970.218.4093



--

Regards,

**Steve Wheeler, P.E.**

**Integrity Engineer**



P 303.894.2100 x5192

1120 Lincoln Street, Suite 801, Denver, CO 80203

[steven.wheeler@state.co.us](mailto:steven.wheeler@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)