

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/26/2024

Submitted Date:

12/06/2024

Document Number:

698602658

**FIELD INSPECTION FORM**

Loc ID 304044 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 305 S RIDGE STREET #6279  
City: BRECKENRIDGE State: CO Zip: 80424

**Findings:**

- 21 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253986	WELL	PR	11/20/1996	GW	125-07864	KLINZMAN 9-11	PR

**General Comment:**

Routine Inspection.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained County Road.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Content/Quantity/Hazard sign at tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well sign at wellhead location.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Well sign posted at remote Gas Meter Run.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No well lease sign posted at remote water processing tank battery located CR 52 & CR U.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	01/01/2025
<b>Emergency Contact Number:</b>			
Comment:	Emergency contact information posted on well sign.		
Corrective Action:		Date:	
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Dried weeds and vegetation around vertical separator and produced water tank.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	Stock panel fencing around surface equipment at shared remote gas metering location.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well location.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Separator	# 1		
Comment:	Inside remote separator shed.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located on CR 52 & CR U. Digital Gas Meter Run. Meter Calibration/Test Log dated 11-13-24. Well Inlet Valve open. Gas Outlet Valve open.		
Corrective Action:			Date:
Type: Dehydrator	# 1		
Comment:	Dehydrator on gas meter run inlet.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Shared Remote Gas Meter Shed.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Remote Separator Shed located on CR 52 & CR U.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing production. Tubing in the wellbore. Tubing valve open. Casing valve not connected.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	PBV FIBERGLASS		,
Comment:	No sign posted at facility. Tank shared with Klinzman 10-11, 125-07970. Remote tank battery is across the CR from remote metering location.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	None.			
Corrective Action:				Date:

**Wells Served By Facilities Above**

**AirsID**

API Number

API Number

AirsID

125-07970

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 253986 Type: WELL API Number: 125-07864 Status: PR Insp. Status: PR

**Producing Well**

Comment: Tubing in wellbore. Tubing valve open. Casing valve not connected. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.  
  
Electronic Well File reflects last Production/Status reported 9/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698602676	Inspection photos.	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6813849">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6813849</a>