

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

03/24/2024

Document Number:

403722243

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

OGCC Operator Number: 10633 Contact Person: James Miller
Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (720) 984-7460
Address: 555 17TH STREET SUITE 3700 Email: jmiller@civiresources.com
City: DENVER State: CO Zip: 80202
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No []

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 332739 Location Type: Well Site
Name: ARISTOCRAT ANGUS FEDERAL Number: 0-4-10
County: WELD
Qtr Qtr: NWSW Section: 10 Township: 3N Range: 65W Meridian: 6
Latitude: 40.237900 Longitude: -104.657370

Description of Corrosion Protection

Crestone pipelines are covered in a protective external coating. Flowlines are subject to thorough inspections and fabrication standards during installation to minimize coating and pipe defects. Crestone maintains a chemical program to reduce internal corrosion. If a flowline is found to lack integrity, Crestone will investigate, report, and remediate any spills in accordance with the 900 series rules.

Description of Integrity Management Program

Crestone flowlines are pressure tested prior to placing flowlines into service. Flowlines are tested on an annual basis in accordance with COGCC 1104 series rules. If a flowline is found to lack integrity, Crestone will investigate the root cause, as well as report and remediate any spills in accordance with the 900 series rules. All repairs will be completed in accordance with COGCC 1102 Series rules.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 478450 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 332739 Location Type: Well Site
Name: ARISTOCRAT ANGUS FEDERAL Number: 0-4-10
County: WELD No Location ID
Qtr Qtr: NWSW Section: 10 Township: 3N Range: 65W Meridian: 6
Latitude: 40.237900 Longitude: -104.657370

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: _____ Date Construction Completed: 06/04/2013
Maximum Anticipated Operating Pressure (PSI): _____ Testing PSI: _____
Test Date: _____

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: _____

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 478452 Flowline Type: Wellhead Line Action Type: Abandonment Verification

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 332739 Location Type: Well Site
Name: ARISTOCRAT ANGUS FEDERAL Number: 0-4-10
County: WELD No Location ID
Qtr Qtr: NWSW Section: 10 Township: 3N Range: 65W Meridian: 6
Latitude: 40.237900 Longitude: -104.657370

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: Native Materials Date Construction Completed: 07/26/2005
Maximum Anticipated Operating Pressure (PSI): 200 Testing PSI: _____
Test Date: _____

OFF LOCATION FLOWLINE Abandonment Verification

Date: 11/09/2023

Abandonment Verification

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).
(No Jurisdiction)

Description of Abandonment Verification:

The flowline (12322840_FL) serviced the ARISTOCRAT ANGUS 1-6-10 (05-123-22840). Flowline (12322840_FL) is co-located in the same trench as the ARISTOCRAT ANGUS FEDERAL 2-4-10 (12330591_FL), so it was abandoned in place as per Rule 1105.e. See attached exhibit for third party verification.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 478448 Flowline Type: Wellhead Line Action Type: _____

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 332739 Location Type: Well Site
Name: ARISTOCRAT ANGUS FEDERAL Number: 0-4-10
County: WELD No Location ID
Qtr Qtr: NWSW Section: 10 Township: 3N Range: 65W Meridian: 6
Latitude: 40.237900 Longitude: -104.657370

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: _____ Date Construction Completed: 06/13/1993
Maximum Anticipated Operating Pressure (PSI): _____ Testing PSI: _____
Test Date: _____

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 11/02/2023

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

Flowline is co-located located in the same trench as the ARISTOCRAT ANGUS FEDERAL 2-4-10 (12330591_FL). Flowline will be abandoned in place as per Rule 1105.d and verified by a third party. See attached exhibit for flowline path.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 478449 Flowline Type: Wellhead Line Action Type: _____

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 336608 Location Type: Well Site
Name: REI Number: 25-10
WELD No Location ID

County: _____ Meridian: 6

Qtr Qtr: SWSW Section: 10 Township: 3N Range: 65W

Latitude: 40.233680 Longitude: -104.657390

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000

Bedding Material: _____ Date Construction Completed: 06/13/1993

Maximum Anticipated Operating Pressure (PSI): _____ Testing PSI: _____

Test Date: _____

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: _____

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 478451 Flowline Type: Wellhead Line Action Type: _____

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 332739 Location Type: Well Site

Name: ARISTOCRAT ANGUS FEDERAL Number: 0-4-10

County: WELD No Location ID

Qtr Qtr: NWSW Section: 10 Township: 3N Range: 65W Meridian: 6

Latitude: 40.237900 Longitude: -104.657370

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000

Bedding Material: _____ Date Construction Completed: 05/11/2010

Maximum Anticipated Operating Pressure (PSI): _____ Testing PSI: _____

Test Date: _____

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: _____

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

OPERATOR COMMENTS AND SUBMITTAL

Comments

Form 44 filed to report POST-ABANDONMENT verification. The following flowline was abandoned in place:
12322840FL: serviced ARISTOCRAT ANGUS1-6-10 (05-123-22840)
Pressure test attached.
Third party verification attached.
Updated GIS data attached.

The 12322840FL was abandoned in place and does not have any associated spill/releases reported on a Form 19.
All other related flowlines will remain as previously reported.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: _____ Date: 03/24/2024 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Director of COGCC Date: _____

Conditions of Approval

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

403722245	THIRD PARTY VERIFICATION
403728261	PROPOSED ABANDONMENT LAYOUT DRAWING
403728268	OFF-LOCATION FLOWLINE GIS SHP
403728328	PRESSURE TEST

Total Attach: 4 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)