

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/22/2024

Submitted Date:

12/06/2024

Document Number:

697602434**FIELD INSPECTION FORM**Loc ID 448774 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448783	WELL	SI	12/01/2023	OW	123-44020	ACCO TERRA STATE 18-36	EI
487141	TANK BATTERY	AC	06/26/2024		-	Acco Terra State 18-36 Facility TB	EI
488499	SPILL OR RELEASE	CL	10/10/2024		-	Acco Terra St 18-36	EI

General Comment:

This is an environmental inspection to determine progress on Spill ID 488499. Inspection submitted to document site conditions at the time of inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

Location				
Overall Good: <input checked="" type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type	STORAGE OF SUPL			
Comment:	Trash and other equipment associated with the decommissioning were littered throughout the location.			
Corrective Action:	Comply with Housekeeping Rule 606.			Date: 12/13/2024
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	OTHER			
Comment:	Fencing around the wellhead excavation did not properly cover the entire excavation.			
Corrective Action:	Operators will fence or cover open trench/excavation to prevent access when sites are not attended Remediation Safety fence Rule 913.b.(5)B.			Date: 12/13/2024
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Environmental					
Waste Management:					
Type	Management	Condition	GPS (Lat) (Long)		
Oily Soil					
Comment	Oily soil was stockpiled with no liner and was not labeled.				
Corrective Action	E&P Waste shall be properly stored, handled, transported, treated, recycled, or disposed per Rule 905.				Date: 12/13/2024
Spill/Remediation:					
Comment:	Staining was observed in multiple areas outside of the excavations. Staining was also observed within the excavation.				
Corrective Action:	In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.				Date: _____
Emission Control Burner (ECB): _____					
Comment: _____					
Pilot: _____ Wildlife Protection Devices (fired vessels): _____					

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697602435	Photolog	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6814295